

## 4 Seasons Home Inspection, LLC

150 Maple Avenue, #128, South Plainfield, NJ 07080 www.4SeasonsHl.com 1-877-547-7383

### buyer # street Town nj xxxxx

Please carefully read the following inspection report in its entirety and the Scope of Inspection. The inspection was a visual inspection and performed accordingly to the New Jersey Standards of Practice 13:40-15.16 in readily accessible areas at time of inspection. Inspection behind walls, ceilings, flooring or other covered surfaces is excluded from a visual home inspection. That would involve destructive measures to see behind them. The home inspection report and any other applicable reports (radon, wood destroying insects) are emailed to you, your attorney or realtor if indicated by initialing appropriate areas on last page of Pre-inspection agreement. If a hard copy was ordered on the last page of your agreement, then and only then will a hard copy be mailed via USPS. Please read all addenda and supplementary attachments. Pursuant to 13:40-15.2 Definitions "Home inspection report," all items in report must not be ignored where recommendations made regarding the need to repair, replace or monitor a system or component, or to obtain examination or evaluation and analysis by a qualified professional, tradesman or service technician. Please call us with any questions or concerns that you may have so that they may be promptly answered before your closing. If recommendations not acted upon or followed up with sellers before closing, it will be solely your responsibility for repairs and costs incurred by not following report recommendations.

### RECEIPT

Inspection Date: June 05, 2015 Friday 10am- 2:45pm

Client Name: buyer (buyer@gmail.com)
Emails: lawyer@lawfirm.com

Inspection Address: # street address town, nj xxxxx

Inspected by: Linda Geczi home inspection lic. #24GI00061500



### THE HOUSE IN PERSPECTIVE

### **BUILDING DATA**

Approximate Age: 2004 (~11yrs.) Style: Single family

Main Entrance Faces: S

State of Occupancy: Occupied
Weather Conditions: Raining, 55 °F

Ground cover: wet, rain past several days

Home Inspection:	\$00
Termite:	INCL.
Radon	\$00
Total:	\$00

Paid by: check #101

Cc: lawyer, Esq.

Main Concerns (p.2) and detailed report follows this page (3-47)

Page 2 of 47

MAIN CONCERNS: Recommend qualified contractors or licensed professionals further evaluate, address defects and/or make repairs before closing. Responsibilities of repairs and negotiations are not part of a home inspection and should be discussed with your Attorney. READ entire REPORT and recommendations before closing.\*\*

- 1. TERMITE/TUBES/STRUCTURE<sup>1</sup>: There were termite tubes on rear right inner wall and tubes on a cabinet and between the drywall and foundation walls adjacent to the family room. Have the drywall removed by structural carpenter and evaluate or rule out for any concealed termite/WDI damage to garage or adjacent areas. The termite shelter tubes were broken open in a few spots and the live termite were visible scattering when opened and light hit them. The garage was packed with storage (floor & perimeter) and inaccessible. Have all storage removed from walls for structural carpenter evaluation & determination of damage, repairs or ruling out hidden/concealed damage. There was rotted trim/frame around the rear kitchen door; have a structural carpenter evaluate for repairs/replacement. Have a building contractor and/or structural carpenter evaluate the family room cracks & bulges wall adjacent to the kitchen and advise.
- 2. FOUNDATION/GAPS/GARAGE<sup>1</sup>: There were gaps around the garage door/foundation junctures. Have a mason repair the gaps, cracks, etc where needed to maintain seals. Recommend replacing weather seals/trim around the garage doors where needed; gaps & torn seals (water & rodent access points). There was missing trim/flashing on roof rake(s); exposed wood trim, flakes paint. There was rotted trim/frame around the rear kitchen door; have a structural carpenter evaluate for repairs/replacement.

3.	<b><u>PERMITS</u></b> : There was a Twp. Permits sticking on the PVC pipe for the sewer ejector pump;
	basement Rough out indicated. Recommend obtaining all closed permits for finished basement
	(several rooms, bathroom, HVAC, electrical, etc.) as required by township before closing.

#### **FOLLOW-UPS:**

- 1. A/C: The outside temperature was 55°F and too cool to test the air conditioning. Recommend testing the A/C when warmer before closing. There was one older/original (11 yrs.) and a newer condenser. There should be at least theree consecutive days & noghts of 60-65F temperatires when using the air conditioner to avoid damaging the condenser unit "Slugging."
- 2. POOL/EQUIPMENT: The pool in yard was not evaluated or its equipment; follow-up with a qualified pool inspector before closing. Pool, spas, etc. beyond the scope of a home inspection.

Pursuant to NJAC 13:40-15.2 Definitions:

<sup>&</sup>quot;Material defect" means a condition, or a functional aspect, of a structural component or system that is readily ascertainable during a home inspection that substantially affects the value, habitability, or safety of the dwelling, but does not include decorative, stylistic, cosmetic, or aesthetic aspects of the system, structure or component.

<sup>\*\*</sup> Any and All recommendations noted in this report either written or verbal, advised either further evaluation, repair and/or replacement should be completed prior to the home inspection contingency expiring and/or any other contractual obligation expires.\*\*

, Page 3 of 47

### REPORT OVERVIEW

# CONVENTIONS USED IN THIS REPORT- ALL SYSTEMS IN HOME MUST BE SERVICED YEARLY AND PROPERLY MAINTAINED AND UPGRADED AS THEY AGE

**SATISFACTORY** - Indicates the component is functionally consistent with its original purpose but show signs of normal wear and tear and deterioration and will need maintenance or repairs at any time over its life. Plan and budget for these repairs, replacement and upgrades. Have systems serviced regularly and maintained.

**MARGINAL** \*- Indicates the component needs repairs, upgrade, monitor and/or replacement anytime over its life. Plan and budget for these repairs, replacement and upgrades. Defects exist- have evaluated and repaired.

**POOR\*** - Indicates the component needs repair or replacement now. Defects exist- have evaluated and repaired.

**SAFETY HAZARD\*** - Denotes a condition that is unsafe and in need of prompt attention now

\*NOTE: All observations or comments reported in this written report should obtain examination and analysis by a qualified professional, tradesman or service technician for that concern, defect or repair prior to closing for cost of repair, replacement or upgrade.

### THE SCOPE OF THE INSPECTION (READ & UNDERSTAND)

All components designated for inspection in the **New Jersey Standards of Practice 13:40-15.16 in readily accessible areas at time of inspection** except as may be noted in the "Limitations of Inspection" sections within this report. It is the goal of the inspection to put a home buyer in a better position to make a buying decision. This inspection should not be considered as an opinion or as advice as whether or not to purchase the property. Not all recommendations will be identified during this inspection. It is not our job or function to fix or solve a problem. We report on the conditions at time of inspection and recommend a specialist to further evaluate and advise on cost of repairs or remedy. Home inspectors are "Generalists" not experts or builders. A home inspection is not a CODE inspection. \*A certificate of occupancy or habitability should be obtained before closing. Township code officers perform code inspections for that certificate; not home inspectors. Code issues may arise that need corrections that are not part of a general home inspection and should be addressed before closing. Unexpected repairs as well as maintenance should still be anticipated. All systems and building structure will age and need repairs regardless of the age of home. Plan and budget accordingly. The inspection is not considered a guarantee or warranty of any kind. It is a snap shot in time and conditions will change with time. A "Home Warranty" is readily available from most realtor offices or on the market to help defray the cost of repairs during the life of a home. We strongly recommend this and all other forms of service plans for HVAC and insurance on sewer and water main lines.

In addition to the NJ standards, please refer to the pre-inspection agreement/contract according to NJAC 13:40-15.15, for a full explanation of the scope of the inspection. All reported items of consideration in this report must be addressed for repair evaluation and cost prior to closing. Any conditions concealed, latent, inaccessible or covered up at time of inspection are NOT the responsibility or liability of the home inspector or company. Walls, ceilings, carpeting, or other forms of coverings or finished surfaces cannot be removed during a non-invasive home inspection. Therefore, to see into walls and below surfaces can only be done with a contractor that can perform invasive inspections. We cannot guess or comment on anything behind coverings and report on non visual or concealed areas. There is always a chance for concealed damage or mold or other structural concerns within walls, floors and ceilings. *If you are not satisfied with a visual inspection, it is* recommended to engage in those services that can open up walls, ceilings or flooring before closing since it cannot be done in a visual home inspection. This is under the law in the New Jersey Standards of Practice 13:40-15.16 for a licensed home inspector in the state of New Jersey.

#### .We Always Miss Some Minor Things

The intent of the inspection is not to find minor problems or cosmetic items. It is to find major problems or defects. The minor problems that are identified were discovered while looking for more significant problems. We may note them simply as a courtesy.

### **Not Insurance or Warranty**

In conclusion, a home inspection is designed to better your odds. It is not designed to eliminate all risk. For that reason, a home inspection should not be considered an insurance policy or warranty.

			CROUNDS	ı	, , Page 4 of 47
			<b>GROUNDS</b>		
SERVICE WAI	LKS	☐ Public sidew	alk needs repair		
Material:	✓ Concrete pavers	_	☐ Gravel	☐ Brick	☐ Other
Condition:	✓ Satisfactory	☑ Marginal_	☐ Poor	☐ Trip Hazard	_
	☐ Pitched toward		ettling	☐ Not visible	☑ Typical cracks
DRIVEWAY/PA			_	_	_
Material:	☐ Concrete	✓ Asphalt	☐ Gravel/Dirt	☐ Brick	Other
Condition:	☐ Satisfactory	✓ Marginal	☑ Repair/Fill cra	cks and seal <b>Settlin</b>	g Cracks ☑ Typical crack
`	ERED ENTRANCE	☑ None			
STOOPS/STEP		☐ Uneven riser		_	
Material:	✓ Concrete/Brick		Other	☐ Railing/Balusters	
Condition:	✓ Satisfactory	☑ Marginal	Poor	☑ Cracks	☑ Settled
	☐ Rotted/Damage	ed .	☐ Safety Hazara	Į.	
PATIO	None				
Material:	✓ Concrete pavers		☐ Kool-Deck®	☐ Brick	☐ Trip hazard
Condition:	Satisfactory	☐ Marginal	□ Poor	☐ Settling Cracks	
	☐ Pitched toward:	s home (See rema	ırks page)	☐ Drainage provided	☐ Typical cracks
DECK/BALCO	ONY (flat, floored, ro	oofless area)	None		
	PORCH COVERS	✓ None	☐ Earth to wood	contact $\Box$	Moisture/Insect damage
FENCE/WALL		d	□ None		
LANDSCAPIN	NG AFFECTING FO		(See remarks page)	)	
Negative Grade			☑ South		
	positive pitch of soil			_	
	d additional backfill		nend window wells/c		back trees/shrubberies
□ Wood in co	ontact with/improper	clearance to soil	☐ Yard drains ob	served - not tested	
☑ <u>NOTE</u> : Sin	nk holes and other G	eological issues a	ire NOT part of a ge	eneral home inspection	!
<u> </u>	(f)1(v) Standards o	· ·	1 0 0	4	
			ng walls with respec	t to their immediate det	rimental effect on the
					, sea walls, break-walls,
	eads and docks, or er				,
RETAINING V	WALL  Mone	Material:	,	☐ Drainage holes re	commended
Condition:	☐ Satisfactory	☐ Marginal	□ Poor	☐ Safety Hazard	☐ Leaning/cracked/bowed
					ions as per the manufacturer
(Deleter to deleter)		hip rules. Obtain a	ıll closed permits for r	etaining walls before clos	sing.
(Relates to the visual o		_			
HOSE BIRS	│ □ None	□ No anti-sinho	on valve		

**Operates:** ☐ Yes □ No ☐ Not tested □ Not on

### GENERAL COMMENTS

**GROUNDS:** Seal gaps, cracks, junctures on driveway and steps where needed. All house junctures should be maintained/caulked to avoid water seepage or wood destroying insects. Recommend maintaining a positive pitch of soil around foundation for proper water drainage. Stones, mulch and vegetation are not recommended around foundation; tends to trap water against foundation and cause wet basements. Trim back or cut away trees, shrubs and branches away from house. Remove trees and or branches too close to roof, structures and electrical cables/communication lines for safety. Overhanging trees and overgrowth can cause mechanical damage, moss, algae, attract carpenter ants, raccoons, squirrels or other animals. Recommend window well covers for all basement windows to keep out water, ice snow and avoid wet basement. The pool in yard was not evaluated or its equipment; follow-up with a qualified pool inspector before closing. The liner was loose or detached at several spots; incidental observations while walking around home. There was water damage on lower door frame off kitchen; have a structural carpenter evaluate/repair. See siding section comments.

1.	<mark>DNCERNS:</mark> Recommend maintaining exterior components; driveway, walks, etc. There was water damage on lower door frame off kitchen; have a structural carpenter evaluate/rep	oair. See sidi
	section comments.	

INSPECTED FROM				ROOF		, , Page 6 of 47
STYLE OF ROOF Type:	ROOF VISIBII	LITY	ll ☑ Partial	□ None	☑ Limited by: Angl	e e
Type:	INSPECTED F	<b>ROM</b> Ro	oof 🔲 Ladder at o	eaves 🗹 Ground	d ( <i>Inspection Limited</i> ) <b>W</b> it	h Binoculars
Roof#1: Type: Asphalt shingles	Type:	☑ Gable				☐ Other
GAF and other manufacturer's architectural roof shingles involved in a class action suit to err on side of caution. Often it cannot be determined by visual inspection. Age of roof is only an approximation. Installer's paperwork is only proof of age. VENTILATION SYSTEM	Roof #1:	Type: Asphalt				years
Satisfactory   Marginal   Poor   Snow covered	GAF and other is cannot be determined VENTILATIO Appears Adequ	manufacturer's a nined by visual in <b>N SYSTEM</b> nate:  Yes	rchitectural roof shir nspection. Age of ro <b>Type:</b> Soffit No Turbine	ngles involved in a pof is only an appro ☑ Ridge	class action suit to err on s eximation. Installer's pape ☐ Gable ☐ Roof	ide of caution. Often it rwork is only proof of age.
VALLEYS Condition:				, condensation/rusted	nails/frost on sheathing & r	afters, heat build-up,
Condition: ☐ Curling ☐ Cracking ☐ Ponding ☐ Burn Spots ☐ Broken/Loose Tiles/Shingles ☐ Nail popping ☐ Granules missing ☐ Alligatoring ☐ Blistering ☐ Missing Tabs/Shingles/Tiles ☐ Moss buildup ☐ Exposed felt ☐ Cupping ☐ Incomplete/Improper Nailing ☐ Multi-layer roof- not recommended ☑ Need more Ventilation to avoid mold, condensation, heat build-up, sheathing/structure damage  READ THIS NOTE: ☑ All roofs if not in perfect LEAK −FREE condition, water can and will leak into a home, causing damage, and mold. Anything checked off above in conditions section must be addressed or corrected and evaluated by a qualified roof prior to closing. Plan for yearly repairs and roof replacement. Obtain the roof warranty from sellers. Water damage and mold can be concealed behind walls, ceilings or any other covering that cannot be seen during a Visual Home Inspection. Refer to the NJ Standards of Practice sent with your Pre-Inspection contract. If you have any concerns, you must engage in a contract with a licensed contractor to open up walls, ceilings, flooring or other cladding or covering by arranging it with the sellers before closing to rule out hidden problems, mold or other water related issues. There are costs associated with this type of invasive investigation. This will involve destructive means that is beyond the scope of a general	VALLEYS	✓ Not visible	□ N/A Material	: Galv/Alum	☐ Asphalt ☐ Lead	
□ Nail popping □ Granules missing □ Alligatoring □ Blistering □ Missing Tabs/Shingles/Tiles □ Moss buildup □ Exposed felt □ Cupping □ Incomplete/Improper Nailing □ Multi-layer roof- not recommended ☑ Need more Ventilation to avoid mold, condensation, heat build-up, sheathing/structure damage  READ THIS NOTE: ☑ All roofs if not in perfect LEAK −FREE condition, water can and will leak into a home, causing damage, and mold. Anything checked off above in conditions section must be addressed or corrected and evaluated by a qualified roof prior to closing. Plan for yearly repairs and roof replacement. Obtain the roof warranty from sellers. Water damage and mold can be concealed behind walls, ceilings or any other covering that cannot be seen during a Visual Home Inspection. Refer to the NJ Standards of Practice sent with your Pre-Inspection contract. If you have any concerns, you must engage in a contract with a licensed contractor to open up walls, ceilings, flooring or other cladding or covering by arranging it with the sellers before closing to rule out hidden problems, mold or other water related issues. There are costs associated with this type of invasive investigation. This will involve destructive means that is beyond the scope of a general	CONDITION (	OF ROOF CO	VERINGS Roof	#1: 🗹 Satisfactor	ry □ Marginal □ Poor	☐ Snow covered
READ THIS NOTE: ✓ All roofs if not in perfect LEAK –FREE condition, water can and will leak into a home, causing damage, and mold. Anything checked off above in conditions section must be addressed or corrected and evaluated by a qualified roof prior to closing. Plan for yearly repairs and roof replacement. Obtain the roof warranty from sellers. Water damage and mold can be concealed behind walls, ceilings or any other covering that cannot be seen during a Visual Home Inspection. Refer to the NJ Standards of Practice sent with your Pre-Inspection contract. If you have any concerns, you must engage in a contract with a licensed contractor to open up walls, ceilings, flooring or other cladding or covering by arranging it with the sellers before closing to rule out hidden problems, mold or other water related issues. There are costs associated with this type of invasive investigation. This will involve destructive means that is beyond the scope of a general	Condition:	☐ Nail poppin	g ☑ Granules miss up ☐ Exposed felt	ing ☐ Alligatoring  Cupping  Need more V	☐ Blistering ☐ I ☐ Incomplete/Improper entilation to avoid mold, con	Missing Tabs/Shingles/Tiles Nailing
	damage, and mo qualified roof pr damage and mol Inspection. Reformust engage in a arranging it with associated with	old. Anything charior to closing. It is can be conceauted to the NJ Standar contract with a contract with a the sellers beforthis type of invalue.	ecked off above in c Plan for yearly repairs led behind walls, cei dards of Practice sen licensed contractor to re closing to rule out sive investigation. T	CEAK –FREE control on ditions section in a sand roof replacent lings or any other cut with your Pre-Intro open up walls, control of the hidden problems, which will involve design of the hidden problems.	dition, water can and will nust be addressed or correc- nent. Obtain the roof warra- covering that cannot be see spection contract. If you he cilings, flooring or other cl mold or other water related structive means that is bey	ted and evaluated by a canty from sellers. Water in during a Visual Home ave any concerns, you adding or covering by I issues. There are costs and the scope of a general

MULTI-LAYER ROOFS: Multi- layers will shorten life of existing roof. There are many disadvantages of having multi-layer roofs even though it may be acceptable in many municipalities across New Jersey. Multi layers wear faster or shorten the current roof layer because of the uneven surface that it was laid over. These roofs are heavier and increase the dead load thereby placing the roof structure under greater load often causing deflection. Deflection was observed from street or distance looking at roof. Multi layers (ML) are more inclined to have shingles blow off especially if nails cannot penetrate the roof decking. The key factor or weakness in ML layer roofs are the fact that flashings are not replaced without stripping off roof. This makes the roof vulnerable in areas where old flashings remain and often tarred over. The sun's UV rays cracks tar year to year and water leaks in these areas. ML roofs tend not to dry out sufficiently and thus accelerating the ageing or deterioration of the newest layer. Flashings are the most important detail of a well installed roof to help protect the junctures and penetrations from water entry. A ML roof lacks new flashings since it was not striped off for their installations. ML roofs will make attic hotter, trap moisture and cause sheathing damage, rot and mold due to trapped heat and moisture. Roofs should have more or maximum ventilation. Have roof, ventilation and gutters evaluated by qualified roofer before closing.					
SKYLIGHTS □ N/A Condition: □ Satisfactory		☐ Not visible ☑ Cloudy or ☐ Snow covered ☑ Dir	or overcast; limited visibility rty		
PLUMBING VENTS		isfactory	□ Poor		
	Conditions reported above	reflect <u>visible</u> portion only	y		
GENERAL COMMENTS  ROOF: Gutters should be cleaned at periodically for leaks. Roof is origin repair roofs immediately if damage of applicable and transferrable. All roof them. Only a roofer should make reservere weather including winter stomand flowing year round for proper drawn and flowing year.	al to the home; check roomecurs. Obtain the closed fs will need repairs at some pairs and not a handyman ms. Ice and snow build-up	f yearly for lifted shingles, or permits for roof from towns he point during the life of the or non-roofer. Always chec	damaged shingles, etc. and always ship and any warranty from roofer if the roof; expect these and plan for ck roofs after rains, high winds or		

Page	8	of	47

## CHIMNEY/GUTTERS/SIDING/TRIM

CHIMNEY(S)	None	Location(s): right sid				
Viewed From:	Roof	Ladder at eaves	Ground with binoculars			
Note: Chimney inspection is very limited during a home inspection. Sections at top, cap, liners are often not visible. Level I chimney inspection is always recommended prior to closing to fully inspect the chimney.						
Rain Cap/Sparl		✓ Yes- rusted	g to fully inspect the chilliney.  ☐ No  ☐ Recommended			
Chase:			cap/arrestor- recommend having evaluated for stainless steel			
Evidence of:	☑ cemented	☑ Cracks	□ Loose mortar joints □ Flaking □ Loose Brick □ Rust			
Flue/Liner:	☐ Tile	☐ Metal	☐ Unlined ✓ Not visible			
Evidence of:	☐ Scaling	☐ Cracks	☐ Creosote ☐ Not evaluated (See remarks page)			
Evidence of.	_	ned and re-evaluated	☐ Recommend Cricket/Saddle/Flashing			
Condition:	☐ Satisfactory	☑ Marginal	☑ Staining			
GUTTERS/SCU	UPPERS/EAVES T	ROUGH ☑ Dirty,	clogged or poorly maintained gutters will cause leaks into			
		interior o	r behind walls. Clean often and checked frequently.			
		<b>☑</b> Needs	to be cleaned yearly or more often $\square$ Downspouts missing			
			oof and prevents melting snow (water) from draining off the roof. home and cause damage to walls, ceilings, insulation, and other			
	ПС	□ xy: 1/p1 .:	<b>7</b> (0.1 : 1/41 : <b>7</b> (0.1			
Material:	☐ Copper	☐ Vinyl/Plastic	☐ Galvanized/Aluminum ☐ Other			
Condition:	☑ Satisfactory	☐ Marginal	☐ Poor ☐ Rusting ☑ Main runs			
Leaking: Attachment:	☑ Corners □ Loose	☑ Joints				
Attachment:  Extension needed		<ul><li>☐ Missing spikes</li><li>☑ South</li></ul>	<ul> <li>☐ Improperly sloped (See remarks page)</li> <li>☑ East</li> <li>☑ West</li> </ul>			
SIDING			(*See remarks page EIFS)			
Material:	☑ Brick siding &	vinyl siding	(			
	☑ Shrubs too close					
	☐ Typical cracks	_	☐ Wood rot ☐ Peeling paint ☐ Loose/Missing/Holes			
Note- Concealed	d behind Siding:	☑ Siding cannot be	removed during a home inspection; invasive. There is always a			
			lamage behind gutters, siding, trim, rake boards and fascia. This			
cannot be detern	nined during a visual	non-invasive home in	spection. Mold can also be concealed and not visible.			
Condition:	☐ Satisfactory	☐ Marginal	□ Poor □ Recommend repair/painting			
TRIM, SOFFIT	, FASCIA, FLASH	IING				
Material:	☑ Wood	☐ Fiberboard	☐ Aluminum/Steel ☐ Fiber Cement ☐ Stucco			
	☐ Recommend rep	air/painting	☑ Damaged wood- around kitchen rear door ☑ Metal/vinyl			
	☐ Other					
			ealed behind gutters on fascia or soffits. Monitor areas and			
	s needed. Dirty gutt	ers will spill over and	cause damage often concealed, on fascia, trim, siding or interior;			
clean regularly.			_			
Condition:	☑ Satisfactory	☐ Marginal	☑ Poor – missing trim at roof rakes/add			
CAULKING						
<b>Condition:</b>	□ Satisfactory	☑ Marginal	☑ Poor- by garage doors			
	☑ Recommend are	und windows/doors/m	asonry ledges/corners/utility penetrations as needed			
WINDOWS &	SCREENS	☐ Failed/fogged in:	sulated glass			
Material:	☑ Wood	Screens:	✓ Not evaluated in a home inspection			
Condition:	☐ Satisfactory	✓ Marginal	□ Poor □ Wood rot □ Recommend repair/painting			
	- Satisfactor,					
STODMS WIN		□ Not in-4-11- 1				
STORMS WIN	DOWS  M/A	□ Not installed  N	☐ Wood ☐ Clad comb. ☐ Wood/metal comb.			

#### GENERAL COMMENTS

CHIMNEY/GUTTERS/SIDING/TRIM: Clean gutters often to ensure proper flow or distribution away from structure. Clogged, dirty or covered (gutters helmets, screens, etc.) will reduce the collection ability and spillage or water damage can occur to interior of home. Gutters and rain leaders or downspouts are important for rainwater collections and distribution away from structure. Vegetation, grading surface drainage, rotted tree stumps among other forms of plant material is likely to adversely affect the home or dwelling adversely. Grounds are viewed during a home inspection from the perspective of how they may affect the home negatively. Homes can typical experience wet basements, crawl spaces and attract Wood destroying insect infestation as a result of negative grading, landscaping and soil too close to home and poor maintenance. Recommend chimney sweep clean/evaluate chimney. All chimneys will need repairs and or linings at some point(s) in their life. Proper maintenance and cleanings are extremely important for fire and life safety as well as maintaining the structural integrity of chimney and or fireplace if present. Framed-rusted metal capping & rain cap/arrestor-recommend having evaluated for stainless steel. It is strongly recommended to have a Level II (National Fire Safety Standard NFPA211) chimney inspection when changing ownerships and when fuels have been changed from oil to gas in older homes to avoid costly repairs and ensure life safety. The Internal elements of the chimney could not be evaluated and fall outside the scope of a visual home inspection. Internal defects and/or fire hazards often exist in any chimney of any age and especially in older structures. It is strongly advised that a Level II Internal chimney inspection be conducted in accordance with the National Fire Safety Standard (NFPA 211) prior to closing. There was rotted trim/frame around the rear kitchen door; have a structural carpenter evaluate for repairs/replacement. There was missing trim/flashing on roof rake(s); exposed wood trim, flakes paint. There was rotted trim/frame around the rear kitchen door; have a structural carpenter evaluate for repairs/replacement.

- 1. Framed- rusted/corrosion drip marks metal capping & rain cap/arrestor- recommend having evaluated for stainless steel
- 2. There was missing trim/flashing on roof rake(s); exposed wood trim, flakes paint. There was rot on rear door frame to yard. There was missing trim/flashing on roof rake(s); exposed wood trim, flakes paint. There was rot on rear door frame to yard.
- 3. There was rotted trim/frame around the rear kitchen door; have a structural carpenter evaluate for repairs/replacement.



Page 10 of 47





Figure 1 Have a structural carpenter evaluate extent of water/rot/damage on rear kitchen door and make repairs.

## EXTERIOR/ELECTRICAL/AC/HEAT PUMP/GARAGE

SERVICE ENTRY  ☑ Underground ☐ Overhead ☐ Weather head/mast needs repair Condition: ☑ Sat.  Exterior outlets: ☑ Yes ☑ No power*- check switches, GFCI's and bathroom GFCI's and recommendation.	•					
Operative: ☐ Yes ☐ No ☐ Overhead wires too low  GFCI present: ☑ Yes Operative: ☐ Yes ☐ No power ☐ Less than 3' from log of the power ☐ Less than 3' from log o	balcony/deck/windows					
V1 ,	☐ Other ☑ Not visible inside walls					
EXTERIOR DOORS       Patio       Storm       Entrance         Weather-stripping:       □ Satisfactory       □ Marginal       □ Poor-garage doors       □ Missing         Door Condition:       □ Satisfactory       □ Marginal       □ Poor	☐ Replace					
<b>EXTERIOR A/C - HEAT PUMP</b> Location(s):						
Unit #1 Brand: American Std. Outside shutoff: ☑ Yes ☑ Newer (6/2014) Unit #2 Brand: Carrier (??? Possibly- name tag rusted off) Outside shutoff: ☑ Yes ☑ Older- original of the shutoff o	ioinal 11 vrs					
Condition:  Satisfactory (Amer. Std.)  Marginal- older unit original  Rusted						
☐ Cabinet/housing rusted Condenser Fins: ☐ Damaged ☐ Need cleaning ☐ Damaged base/p	pad					
GARAGE						
□ None □ Attached □ 3 doors □ 1-car- manual □ 2-car w/ door openers  Automatic Opener: □ Yes □ No □ Operable □ Inoperable □ Remote not available						
Automatic Opener:	afety hazard					
✓ Electric eye- worked	noty nazara					
Roofing Material: ☐ Same as house						
,	☑ Clean & extend					
	□ Vinyl					
	☐ Vinyl					
Floor: Material:  Concrete  Storage, clutter on floor & perimeter- inaccessible- removed  Perimeter needs to be clear for the structural carpenter's eval						
before closing.	ruation of termite damage					
	mmend evaluation/repair					
Burners less than 18" above garage floor: ☑ N/A ☐ Yes ☐ No ☐ Safety hazard	•					
Sill Plates:						
Overhead doors: $\square$ N/A $\square$ Wood $\square$ Fiberglass $\square$ Masonite $\square$ Metal $\square$ Recommend repairs $\square$ N/A						
☑ Satisfactory ☐ Marginal ☐ Poor ☐ <i>Overhead door hardware loose</i> ☐ O Recommend Painting Inside & Edges: ☐ Yes ☑ No ☐ Recommend lubrication ☑ Weather-stripp						
Exterior Service Door:  None	mig missing/damaged					
Electricity Present: $\square$ Yes $\square$ No $\square$ Not visible GFCI Present: $\square$ Yes $\square$ No Operates: $\square$ Yes						
Reverse polarity: ☐ Yes ☑ No Open ground: ☐ Yes ☑ No ☐ Safety hazard						
☐ Handyman/extension cord wiring						
Firewall (Between garage & living area: $\square$ N/A $\square$ Present $\square$ Missing						
☐ Satisfactory ☐ Safety hazard(s) ☐ Recommend repair ☐ Holes walls/ceiling						
Fire door: $\square$ Not verifiable $\square$ Not a fire door $\square$ Needs repair $\square$ Satisfactory $\square$ Inoperative $\square$ Missing	factory  \[ \sum Needs repair \]					
Moisture Stains Present: ☐ Yes ☑ No/inaccessible Typical Cracks: ☑ Yes ☐ No						

#### GENERAL COMMENTS

EXTERIOR/ELECTRICAL/A/C/HEAT PUMP/GARAGE: The trim around the garage doors were torn and need replacement to keep out rodents, water, weather elements. Mice and rodents can chew on electrical wiring and cause damage and health issues. There were wide gaps around the foundation (cement) and garage doors; have a structural mason evaluate/repair; water, rodents, insects can enter these gaps. Recommend having the garage door auto reverse devices adjusted for safety on both doors; did not work. There was termite tubes on rear right inner wall and tubes on a cabinet and between the drywall and foundation walls adjacent to the family room. Have the drywall removed by structural carpenter and evaluate for any concealed termite/WDI damage. The termite shelter tubes were broken open in a few spots and the live termite were visible scattering when opened. The garage was packed with storage (floor & perimeter) and inaccessible. Have all storage removed from walls for structural carpenter evaluation & determination of damage, repairs or ruling out hidden damage.

- 1. There was termite tubes on rear right inner wall and tubes on a cabinet and between the drywall and foundation walls adjacent to the family room. Have the drywall removed by structural carpenter and evaluate for any concealed termite/WDI damage. The termite shelter tubes were broken open in a few spots and the live termite were visible scattering when opened. The garage was packed with storage (floor & perimeter) and inaccessible. Have all storage removed from walls for structural carpenter evaluation & determination of damage, repairs or ruling out hidden damage.
- 2. There were gaps & exposed wood/door framing around garage doors; potential water, insect and rodent entry points. Recommend a building contractor evaluate for repairs/flashings/wrapping etc.
- 3. Pressure reverse-needs to be adjusted & retest safety devices on both doors for safety.














Figure 2 Garage had wall to wall & perimeter storage everywhere; inaccessible. Have removed and inspected for termite & structure before closing. See NPMA-33 Termite report.







This confidential report is prepared exclusively for Client on contract for them to rely on and not transferrable.


© 2010 4 Seasons Home Inspection, LLC

Page 16 of 47

















Page 23 of 47



Page	24	of	47

## KITCHEN

COUNTERTOPS	☑ Sa	atisfactory l	☐ Marginal	☐ Recommend repair	ir/caulking
CABINETS  Satisfactory  Marginal  Recommend repair/adjustment  Note: Counter tops, cabinets or other storage built in products vary in quality, construction, manufacturer and brand. Low quality materials such as press board or particle board type products will sag, bow, glue separation, split have separations between units, counter tops and back splashes. This is especially true when items such as microwave, heavy cookware and other counter top appliances are placed on the shelves and counter tops. They will stress the material, often fall apart and become unglued. It is not the inspector's responsibility to judge them, inspect quality or predict their life or resulting product breakdown. This material and similar composite materials is lower quality and will have problems or negative issues. They often result in loose hardware, splits and cracks due to the low product quality. If the material becomes moist or wet it will swell, split, break down and fail. If you have concerns about your quality of fixtures, brands, manufacturer, appliances, cabinets, counter tops, and other installed products, address them before closing with the selling party. Check all paperwork, manuals and other product literature for specifications, design, construction and warranty.  PLUMBING COMMENTS  Faucet Leaks:  No Pipes leak/corroded: Yes					
Sink/Faucet:	✓ Replace		☐ Chipped	☐ Cracked	☑ Recommend repair
Functional Drainage Hot water: ☑ Yes ☐ WALLS & CEILING	l No Cold	water: 🗹 Yes		✓ Adequate	□ Poor
Condition: $\square$ S	Satisfactory 🗹 M	larginal l	□ Poor	☑ Typical cracks	☐ Moisture stains
HEATING / COOLI			□ No	_	_
Condition: $\square$ S	Satisfactory 🗹 M	larginal l	□ Poor	☑ Sloping	✓ Squeaks
☑ Disposal Ope ☑ Dishwasher Ope Dishwasher Air gap: Outlets Present:	of inspection (Snap appliances. Alway closing. Contents rates:  Yes rates:  Yes Yes Yes	o Shot); obtain of scheck under roof home not made No No No No No	a Home Warranty refrigerators and di inipulated and mov ☑ Oven/Range Dishwasher Dra Operable:	from Realtors office of ishwashers for leaks, oved in a visual home in Operates:  in Line Looped:	<del>-</del> .
G.F.C.I.: Open ground/Revers	✓ Yes	□ No	Operable: ☐ Yes ☑ No	✓ Yes □ No □ Potential safety ha	uzand(s)
NOTE: The Consum appliances of \$547 million  * Pursuant to 13  1) When inspectin  1. Inspect:  v. Hou	er Product Safety aused more than in dollars in proper :40-15.16 Standar g the interior of a range is sehold appliances (1) The kitchen range microwave ovens	Commission, under the damage. Goods of practice residential builds limited to: and oven to and the operation determine water	to (http://www.co	om 2006 through 2008 r, resulting in 3,670 in sumerreports.org) to the shall:  on of burners or heating eycles and appliance times.	3, says that major njuries, 150 deaths, and o see recent recalls.

#### GENERAL COMMENTS

**KITCHEN:** There was corrosion on plumbing under the sink on fittings and piping. There was water dripping on the house of the sink fixtures; have replaced and seal around the counter top/base junctures. Water was dripping on the underside of the counter top/water stained; caulk around the base when faucet replaced. The disposer was noisy; evaluate for repair/replacement. Recommend a switch guard on the disposer to avoid accidently tuning on. Always run cold water when disposer in use to avoid damaging the motor. Have a licensed plumber evaluate the plumbing & disposer and make repairs/upgrades where needed. Ask if there are screens for the windows in home where missing or not installed. Caulk/seal the backsplash/counter top junctures; gaps open for water entry. The appliances are older; upgrade/replace as needed. Typical manufacturer's warranty is ~ 1-2 yrs.; appliances appear much older. There was rotted trim/frame around the rear door; have a structural carpenter evaluate for repairs/replacement. See siding section comments. There was a skylight in kitchen; check periodically for leaks, flaking paint, etc. and address if leaking occurs.

- 1. There was rotted trim/frame around the rear kitchen door; have a structural carpenter evaluate for repairs/replacement.
- 2. Have a licensed plumber evaluate plumbing (fixture/leaking, corrosion, noisy dosposer, etc.) and make repairs & upgrades where needed.

Page 2	26 o	f 47
--------	------	------

## LAUNDRY ROOM

ROOM COMPONEN	TS				
Laundry sink:	□ N/A	Faucet leak	s: ☐ Yes	☑ No Pipes leak:	☐ Yes ☑ No
<b>Hot water: ☑</b> Yes <b>□</b> 1	No	<b>Cold water: ☑</b> Yes	□ No		
<b>Cross connections:</b>	☐ Yes	✓ No Heat source	present: 🗹 Yes	☐ No Room vente	ed: 🗹 Yes 🛚 No
Dryer vented:	□ N/A	<b>☑</b> Wall	☐ Ceiling	☐ Floor	☐ Not vented
	□ Not ven	ited to Exterior	☐ Recommend r	repair	☐ Safety hazard
Electrical:	Open grou	nd/reverse polarity wi	thin 6' of water:	☐ Yes ☐ No	☐ Safety hazard
G.F.C.I. present:	☐ Yes	☑ No <b>Operates:</b>	☐ Yes ☐ No		
<b>Appliances: ☑</b> Washe	er 🗹 Dryer	· 🗹 Cluttered			
Always check under wa	sher & drye	er for water damage an	d mold before clos	sing; contents not mar	nipulated or moved in a
visual inspection.					
<b>☑</b> Note: Testing/inspe	ecting wash	er and dryer is not p	art of New Jersey	y home inspection.	
Washer hook-up lines/		☐ Leaking	☐ Corroded	☐ Not visible	
Gas Shut-off Valve:	$\square$ N/A	<b>☑</b> Yes	□ No □ Cap No	eeded   Safety haz	zard 🔲 Not visible
Electrical Set-up:	☑ N/A	☐ Yes	□ No		
GENERAL COMMEN	NTS				
LAUNDRY OFF KITI	HCEN & G	GARAGE: See garage	section comments	s; termite tubes in gara	nge.

Page	27	of	47

## **BATHROOMS**

BATH: ½ BATH					
SINKS / TUBS / SHOWERS  Faucet leaks: ☐ Yes ☑ No  Fixture(s) Condition:  Hot water: ☑ Yes ☐ No  TOILET  Bowl Loose: ☐ Yes ☑ No	Loose: ☐ Yes ☐ Satisfactory Cold water: ☑ Yes Operates: ☑ Yes		Pipes leak: ☐ Poor ks ☐ Cracked bow	☐ Yes ☑ No    Vank ☐ Cross connection	
WALLS / CEILING / CABINET	TS				
Moisture stains present: G.F.C.I. Present: Open ground/Reverse polarity w	☐ Yes ☑ No ☑ Yes ☐ No	Outlets present: Operates: ☐ Yes ☑ No P	✓ Yes □ No	s present: ☐ Yes ☑ No	
HEATING / COOLING SOURCE Window/Door: ✓ Yes ☐ No Exhaust Fan: ✓ Yes ☐ No	✓ Yes ✓ Satisfactory Operates:	☐ No ☐ Marginal ☑ Yes ☐ No	□ Poor Noisy: □ Yes	☑ No	
GENERAL COMMENTS					
1/2 BATH: If the outlet trips, it re	sets in the garage on th	e GFCI outlet.			
BATH: MASTER BATH SINKS / TUBS / SHOWERS					
Faucet leaks: ☐ Yes ☑ No	Loose:	☑ No	Pipes leak:	☐ Yes ☑ No	
Fixture(s) Condition: Hot water: ☑ Yes ☐ No	☐ Satisfactory  Cold water: ☐ Yes	✓ Marginal	□ Poor		
TOILET	Cold water. En 163	□ 110			
<b>Bowl Loose:</b> ☐ Yes ☑ No	<b>Operates:</b> ✓ Yes	☐ No ☐ Toilet lead	ks	l/tank	
SHOWER / TUB AREA / SINK Material:		lass ☐ Poor Where: all juncture ☐ Poor	☐ Masonite ☐ Rotted floors es Functional Flow:	☐ Other  ✓ Adequate ☐ Poor	
<u>e</u>	☐ Yes ☐ No	Access panel to pu		☐ Yes ☐ No	
☑ Frameless shower doors can shatter or break when coming in contact with other hard objects. Use with caution.					
WALLS / CEILING / CABINET		O-4lots	<b>□ V</b> □ N-		
Moisture stains present: G.F.C.I. Present:	☐ Yes ☑ No ☑ Yes ☐ No	Outlets present: Operates:	<ul><li>✓ Yes</li><li>✓ Yes</li><li>✓ No</li></ul>		
Open ground/Reverse polarity w			otential safety hazard	s present: ☐ Yes ☑ No	
HEATING / COOLING SOURCE	CE ✓ Yes	□ No			
3377 1 /D 🗖 37 🗖 37					
Window/Door: ✓ Yes ☐ No	✓ Satisfactory	☐ Marginal	□ Poor		
Window/Door: ✓ Yes ☐ No Exhaust Fan: ✓ Yes ☐ No	✓ Satisfactory <b>Operates:</b>	☐ Marginal ☐ Yes ☐ No		☑ No	
	•			☑ No	

				, , Page 28 of 47
JACK N JILL BATH:				
SINKS / TUBS / SHOWERS  Faucet leaks: ☐ Yes ☑ No  Fixture(s) Condition:  Hot water: ☑ Yes ☐ No  TOILET	Loose: ☐ Yes ✓ Satisfactory Cold water: ✓ Yes	☑ No ☑ Marginal □ No	Pipes leak: □ Poor	☐ Yes ☑ No
Bowl Loose: ☐ Yes ☑ No	<b>Operates:</b> ✓ Yes	☐ No ☐ Toilet lea	ks 🗆 Cracked bo	wl/tank
SHOWER / TUB AREA / SINK Material:	tic		Functional Flow	
✓ Frameless shower doors can			_	
WALLS / CEILING / CABINET Moisture stains present: G.F.C.I. present: Open ground/Reverse polarity w	<ul> <li>✓ Yes</li> <li>✓ Yes</li> <li>✓ Yes</li> </ul>	Outlets present: Operates:	✓ Yes □ No ✓ Yes □ No ✓ Yes □ No otential safety hazar	
HEAT / COOLING SOURCE Window/Door: ✓ Yes ☐ No Exhaust Fan: ✓ Yes ☐ No	✓ Yes □ No ✓ Satisfactory Operates:	☐ Marginal ☑ Yes ☐ No	□ Poor Noisy: □ Ye	s 🗹 No
GENERAL COMMENTS  JACK N JILL BATH: The toile deposits on fixtures/plumbing thro having water tested for hardness b contractor evaluate damage & male CONCERNS:  1. There was drywall water dam Discuss options to tile to the concern of the contract of the	sughout the home; indi y a water softener come and repairs. Discuss mage from shower/tukedge of wall to protec	cative of hard water, npany. There was dr options to tile to the o; have a contractor t from water damage	See plumbing sec ywall water damage edge of wall to pro evaluate damage ge.	tion comments. Recommend e from shower/tub; have a otect from water damage.

				, , Page 29 of 47
BATH: BEDROOM #4FRONT LEFT				
SINKS / TUBS / SHOWERS  Faucet leaks: ☐ Yes ☑ No  Fixture(s) Condition:  Hot water: ☑ Yes ☐ No  TOILET	Loose: ☐ Yes ☐ Satisfactory Cold water: ☑ Yes		Pipes leak: ☐ Poor	☐ Yes ☑ No
		☐ No ☐ Toilet leal	ks ⊔ <i>Cracked bow</i>	ol/tank
SHOWER / TUB AREA / SINK Material: ✓ Ceramic/Plas Condition: ☐ Satisfactory Caulk/Grouting Needed: Functional Drainage: Whirlpool Operable: ✓ N/A		glass  Poor  Where: all juncture Poor  Access panel to pu	Functional Flow:	☐ Other  ✓ Adequate ☐ Poor ☐ Yes ☐ No
☑ Frameless shower doors can s		n coming in contact	with other hard ol	ojects. Use with caution.
WALLS / CEILING / CABINET Moisture stains present: G.F.C.I. present: Open ground/Reverse polarity w	☐ Yes ☐ No ☑ Yes ☐ No	Outlets present: Operates: ☐ Yes ☑ No Po	✓ Yes □ No ✓ Yes □ No otential safety hazard	s present: ☐ Yes ☑ No
HEAT / COOLING SOURCE Window/Door: ✓ Yes □ No Exhaust Fan: ✓ Yes □ No	✓ Yes □ No ✓ Satisfactory  Operates:	☐ Marginal ☑ Yes ☐ No	☐ Poor Noisy: ☐ Yes	☑ No
BATH BEDROOM #4: There was hard water. See plumbing section		eral deposits on fixtu	res/plumbing throug	hout the home; indicative of

				, , Page 30 of 47
BATH: BASEMENT				
SINKS / TUBS / SHOWERS  Faucet leaks: □ Yes ☑ No  Fixture(s) Condition:  Hot water: ☑ Yes □ No  TOILET	Loose: ☐ Yes ☐ Satisfactory Cold water: ☑ Yes	☑ No ☑ Marginal □ No	Pipes leak: □ Poor	□ Yes ☑ No
	<b>Operates:</b> ✓ Yes	☐ No ☐ Toilet lea	ks	ol/tank
SHOWER / TUB AREA / SINK Material:	tic □ Fiberg ☑ Marginal		☐ Masonite actures on shower par	☐ Other nels- have properly secured
Caulk/Grouting Needed: Functional Drainage: Whirlpool Operable: ☑ N/A	✓ Yes □ No ✓ Adequate □ Yes □ No	Where: all junctur ☐ Poor Access panel to pu	Functional Flow: amp/motor:	☐ Yes ☐ No
☑ Frameless shower doors can see WALLS / CEILING / CABINET Moisture stains present: G.F.C.I. present: Open ground/Reverse polarity was a see where the second of the seco	□ Yes □ No □ Yes □ No	Outlets present: Operates:	t with other hard ob ☐ Yes ☐ No ☑ Yes ☐ No Potential safety hazard	
HEAT / COOLING SOURCE Window/Door: ✓ Yes ☐ No Exhaust Fan: ✓ Yes ☐ No GENERAL COMMENTS	✓ Yes ☐ No ☐ Satisfactory Operates:	☐ Marginal ☑ Yes ☐ No	□ Poor Noisy: □ Yes	□ No
BATH BATHROOM: Obtain all junctures on shower panels- have p				ed by the township. loose
	DIN	ING ROOM	7	
LOCATION: REAR LEFT Walls & Ceiling: ✓ Satisfactory Moisture stains		⊠N	o Where:	
Floor: ☐ Satisfactory  Typical cracks:  Ceiling Fan: ☐ N/A	☐ Satisfact	ory $\square$ N	o Iarginal 🗆	Poor
Electrical: Switches: ☐ You Open ground/Re Heating/Cooling Source: ☑ You Bedroom Egress Restricted: ☑	everse polarity:	Outlets:         ✓ Yes           ☐ Yes         ✓ No           Holes:         ☐ Doo           ☐ No	☐ Cover plates mis	ates: ☑ Yes ☐ No ssing ☐ Safety Hazard Ceilings
Doors & Windows: Open	ational: ☑ Yes s/Latches Operable:		n Vapor Seals: ☐ Ye ☐ Missing ☐	
DINING ROOM:				

Page 31 o	of 4	7
-----------	------	---

## LIVING ROOM

LOCATION:	FRONT LEFT					
Walls & Ceiling	g: 🗹 Satisfactory	☐ Marginal		☐ Poor		
	Moisture stains:	☐ Yes		☑ No	Where:	
Floor:	☐ Satisfactory	☑ Marginal		☐ Poor	☑ Squeaks	☑ Slopes
	Typical cracks:	✓ Yes		□ No		
Ceiling Fan:	☑ N/A	☐ Satisfacto	ory	☐ Margin	al 🗆 Poor	
Electrical:	Switches:	□ No	<b>Outlets:</b>	✓ Yes	☐ No <b>Operates:</b>	✓ Yes □ No
	Open ground/Reverse po	larity:	☐ Yes	☑ No □	Cover plates missing	☐ Safety Hazard
Heating/Cooling	ı <b>g Source: </b> ☑ Yes	□ No	<b>Holes:</b>	☐ Doors	☐ Walls ☐ Ceilin	ngs
Bedroom Egre	ss Restricted: 🗹 N/A	☐ Yes	□ No			
Doors & Wind	ows: Operational:	✓ Yes	□ No	Broken Vapo	or Seals: 🛮 Yes 🗹 1	No
	Locks/Latches	Operable:	✓ Yes	□ No	☐ Missing ☐ Cracl	ked Glass
GENERAL CO	OMMENTS					

**LIVING ROOM:** 

Page	32	of	47

### **FAMILY ROOM**

LOCATION:	REAR RIGI	HT					
Walls & Ceiling	🛚 🗹 Satisfac	ctory	☐ Marginal		Poor-	- cracks & bulged wal	1
	Moisture	stains:	☐ Yes		☑ No	Where:	
Floor:	✓ Satisface	ctory	☑ carpeting	,	☐ Poor	☐ Squeaks	☐ Slopes
	Typical ci	racks:	✓ Yes		✓ No	_	_
Ceiling Fan:	☑ N/A		☐ Satisfacto	ory	☐ Marg	inal 🗆 Poor	•
Electrical:	Switches:	✓ Yes	□ No	<b>Outlets:</b>	✓ Yes	☐ No <b>Operates:</b>	✓ Yes □ No
	Open grou	nd/Reverse po	larity:	☐ Yes	☑ No □	Cover plates missing	☐ Safety Hazard
Heating/Coolin	g Source:	✓ Yes	□ No	Holes:	☐ Doors	☐ Walls ☐ Ceili	ings
Bedroom Egre	ss Restricted	d: ☑ N/A	☐ Yes	□ No			
Doors & Wind	ows:	Operational:	✓ Yes	□ No	Broken Va	por Seals: ☐ Yes 🗹	No □ N/A
		Locks/Latches	Operable:	Yes	□ No	☐ Missing ☐ Crac	ked Glass


### GENERAL COMMENTS

**FAMILY ROOM RIGHT:** There is a gas fireplace in this room; logs had heavy soot and cracked logs; heat damage. Recommend having a fireplace company and licensed plumber evaluate the gas/air fuel and components. There were cracks on the upper wall and bulging under cracks by kitchen/family room wall; have a structural carpenter evaluate to rule out any concealed structural or wood destroying insect damage before closing. See garage section comments & NPMA-33 report. There were speakers in ceiling and/or other rooms in the home; follow up with sellers for all audio equipment.

- 1. Have a building contractor and/or structural carpenter evaluate the cracks & bulges wall adjacent to the kitchen. Have a structural carpenter evaluate garage & adjacent or finished areas to rule out concealed or hidden termite damage. See garage section comments and the NPMA-33 Termite report.
- 2. Recommend having the gas fireplace turned on and tested before closing. There is a gas fireplace in this room; logs had heavy soot, heat damage and cracked logs. Recommend having a fireplace company and licensed plumber evaluate the gas/air fuel mix/ratio and components.

, , Page 33 of 47





Page 34 of 47





This confidential report is prepared exclusively for Client on contract for them to rely on and not transferrable.

© 2010 4 Seasons Home Inspection, LLC

Page	35	of	47
------	----	----	----

### **OFFICE FRONT RIGHT ROOM**

LOCATION:			
Walls & Ceiling: ✓ Satisfactory	☐ Marginal		□ Poor
Moisture stains:	☐ Yes		☑ No Where:
Floor:	☑ Clutters, v	vall to wall	ll furniture □ Poor   ☑ Squeaks  ☑ Slopes
Typical cracks:	✓ Yes		□ No
Ceiling Fan: ☑ N/A	☐ Satisfactor	ry	☐ Marginal ☐ Poor
<b>Electrical:</b> Switches: ✓ Yes	□ No	<b>Outlets:</b>	✓ Yes □ No <b>Operates:</b> ✓ Yes □ No
Open ground/Revers	e polarity:	☐ Yes	✓ No ☐ Cover plates missing ☐ Safety Hazard
<b>Heating/Cooling Source:</b> ✓ Yes	□ No	<b>Holes:</b>	□ Doors □ Walls □ Ceilings
<b>Bedroom Egress Restricted:</b> ✓ N/A	A □ Yes	□ No	-
Doors & Windows: Operation	al: 🗹 Yes	□ No	Broken Vapor Seals: ☐ Yes ☑ No ☐ N/A
Locks/Lat	ches Operable:	✓ Yes	☐ No ☐ Missing ☐ Cracked Glass
CENERAL COMMENTS			

**OFFICE FRONT RIGHT ROOM:** 

							, , Page 36 of
			MASTE	R BE	DROOM		,,
LOCATION:	REAR LEE	T					
Walls & Ceilir			□ Marginal		☐ Poor		
vvans & Cenn	Moisture	•	☑ Further e		☑ No	Where:	
Floor:	☐ Satisfa		✓ Marginal		☐ Poor	✓ Squeaks	☑ Slopes
. 1001	Typical c		✓ Yes		□ No	E Squeaks	El Stopes
Ceiling Fan:	✓ N/A	i acks.	☐ Satisfacto	<b>327</b> 7	☐ Margina	1 □ Po	0.5
Cennig Fan: Electrical:	Switches:	✓ Vos		Outlets:			: ☑ Yes ☐ No
Electrical:				☐ Yes			
(I a a <del>t' - a a</del> /C a a l'		ind/Reverse po	•				g Safety Hazard
Heating/Cool	_	✓ Yes	□ No	Holes: ✓ No	□ Doors □	☐ Walls ☐ Ce	nings
Bedroom Egr			☐ Yes		D 1 W	C 1 🗆 W 👨	7 NT
Doors & Win	aows:	Operational:	✓ Yes	□ No		r Seals: ☐ Yes 🖸	
		Locks/Latches	s Operable:	✓ Yes	□ No □	☐ Missing ☐ Cra	acked Glass
GENERAL C	COMMENTS						
MASTER BE	DROOM: T	here was patche	ed ceiling in th	ne inner sitt	ting; as for histo	orv. *	
		#2 BEL	PROOM	RIGH	T FRONT	BUIS	
I OCATION:	FROTN RT	BOY					
	ng: 🗹 Satisfa	ctory	☐ Marginal		□ Poor		
Walls & Ceilir	ng: ☑ Satisfa Moisture	ctory stains:	☐ Yes		☑ No	Where:	_
Walls & Ceilir	ng: ☑ Satisfa Moisture ☐ Satisfa	ctory stains: ctory	☐ Yes ☑ Marginal		☑ No □ Poor	Where: ☑ Squeaks	☑ Slopes
Walls & Ceilin Floor:	ng: ☑ Satisfa Moisture ☐ Satisfa Typical c	ctory stains: ctory	☐ Yes ☑ Marginal ☑ Yes		☑ No □ Poor □ No	☑ Squeaks	•
Walls & Ceilin Floor: Ceiling Fan:	ng: ☑ Satisfa  Moisture ☐ Satisfa  Typical c ☑ N/A	ctory stains: ctory racks:	☐ Yes ☑ Marginal ☑ Yes ☐ Satisfactor		☑ No □ Poor □ No □ Margina	☑ Squeaks	or
Walls & Ceilin Floor: Ceiling Fan:	ng: ☑ Satisfa Moisture ☐ Satisfa Typical c	ctory stains: ctory racks:	☐ Yes ☑ Marginal ☑ Yes	ory Outlets:	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☐	☑ Squeaks  l □ Po I No <b>Operates</b>	or ∷ ☑ Yes □ No
Walls & Ceilin Floor: Ceiling Fan:	ng: ☑ Satisfa  Moisture □ Satisfa  Typical c ☑ N/A  Switches:	ctory stains: ctory racks:	☐ Yes ☑ Marginal ☑ Yes ☐ Satisfacto ☐ No	ory	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☐	☑ Squeaks  l □ Po I No <b>Operates</b>	or
Walls & Ceilin Floor: Ceiling Fan: Electrical:	ng: ☑ Satisfa  Moisture  ☐ Satisfa  Typical c  ☑ N/A  Switches:  Open grou	ctory stains: ctory racks:	☐ Yes ☑ Marginal ☑ Yes ☐ Satisfacto ☐ No	ory Outlets:	<ul> <li>✓ No</li> <li>□ Poor</li> <li>□ No</li> <li>□ Margina</li> <li>✓ Yes</li> <li>☑ No</li> <li>□ C</li> </ul>	☑ Squeaks  l □ Po I No <b>Operates</b>	or :: ☑ Yes ☐ No g <b>☐ Safety Hazard</b>
Walls & Ceiling Floor: Ceiling Fan: Electrical: Heating/Cool: Bedroom Egr	ng: ☑ Satisfa  Moisture ☐ Satisfa  Typical c ☑ N/A  Switches: Open grouing Source:	ctory stains: ctory racks:  Yes und/Reverse po Yes	☐ Yes ☑ Marginal ☑ Yes ☐ Satisfacto ☐ No	ory <b>Outlets:</b> □ Yes	✓ No	☐ Squeaks  l ☐ Po ☐ No Operates Cover plates missin ☐ Walls ☐ Ce	or :: ☑ Yes ☐ No g ☐ <b>Safety Hazard</b> ilings
Walls & Ceilin Floor: Ceiling Fan: Electrical: Heating/Cool Bedroom Egr	ng: Satisfa Moisture Satisfa Typical c N/A Switches: Open grouing Source:	ctory stains: ctory racks:  Yes und/Reverse po Yes	☐ Yes ☑ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No	Outlets: ☐ Yes Holes:	✓ No	☐ Squeaks  l ☐ Po ☐ No Operates Cover plates missin ☐ Walls ☐ Ce	or :: ☑ Yes ☐ No g ☐ <b>Safety Hazard</b> ilings
Walls & Ceilin Floor: Ceiling Fan: Electrical: Heating/Cool Bedroom Egr	ng: Satisfa Moisture Satisfa Typical c N/A Switches: Open grouing Source:	ctory stains: ctory racks:  Yes und/Reverse po Yes d: N/A	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes	Ory Outlets: □ Yes Holes: ☑ No	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☑ No ☐ Doors ☐ Broken Vapor	☑ Squeaks  l □ Po ☐ No <b>Operates</b> Cover plates missin	or  ::  Yes  No  g  Safety Hazard  illings  No  N/A
Walls & Ceilin Floor: Ceiling Fan: Electrical: Heating/Cool Bedroom Egr Doors & Win	ng: ☑ Satisfa  Moisture  ☐ Satisfa  Typical c  ☑ N/A  Switches: Open grouing Source: ess Restricte dows:	ctory stains: ctory racks:  Yes ind/Reverse po Yes d: N/A Operational: Locks/Latches	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes	Ory Outlets: Yes Holes: No	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☑ No ☐ Doors ☐ Broken Vapor	☑ Squeaks  l □ Po □ No Operates cover plates missin □ Walls □ Ce r Seals: □ Yes ☑	or  ::  Yes  No  g  Safety Hazard  illings  No  N/A
Walls & Ceilin Floor: Ceiling Fan: Electrical: Heating/Cool Bedroom Egr Doors & Win GENERAL C	ng: ☑ Satisfa  Moisture  ☐ Satisfa  Typical c  ☑ N/A  Switches: Open grouing Source: ess Restricte dows:	ctory stains: ctory racks:  Yes und/Reverse po Yes d: N/A Operational: Locks/Latches	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes S Operable:	Outlets:  Yes Holes:  No No Yes	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☑ No ☐ Doors ☐ Broken Vapor ☐ No ☐ C	☑ Squeaks  l □ Po No Operates cover plates missin Walls □ Ce r Seals: □ Yes ☑ Missing □ Cra	or  :: ☑ Yes ☐ No  g ☐ <b>Safety Hazard</b> illings  ☑ No ☐ N/A  acked Glass
Walls & Ceiling Floor: Ceiling Fan: Electrical: Heating/Cool: Bedroom Egr Doors & Win GENERAL C	Moisture  ☐ Satisfa  Typical c  ☑ N/A  Switches: Open grouing Source: ess Restricte dows:  COMMENTS  M RIGHT F	ctory stains: ctory racks:  Yes und/Reverse po Yes d: N/A Operational: Locks/Latches RONT BOYS:	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes S Operable:	Ory Outlets: Yes Holes: No No Yes Yes	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☐ ☐ No ☐ C ☐ Doors ☐ Broken Vapor ☐ No ☐	☑ Squeaks  l □ Po No Operates cover plates missin □ Walls □ Ce r Seals: □ Yes ☑ □ Missing □ Cra	or  :: ☑ Yes ☐ No  g ☐ <b>Safety Hazard</b> ilings  ☑ No ☐ N/A  acked Glass  ome; yellowed/original.
Walls & Ceiling Floor: Ceiling Fan: Electrical: Heating/Cool: Bedroom Egr Doors & Win GENERAL C #2 BEDROO! Smoke & CO	Moisture  ☐ Satisfa  Typical c ☐ N/A  Switches: Open grouing Source: ess Restricte dows:  COMMENTS M RIGHT Forelated equipments	ctory stains: ctory racks:  Yes und/Reverse po Yes d: N/A Operational: Locks/Latches RONT BOYS: ment is not part	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes S Operable:	Ory Outlets: Yes Holes: No No Yes Yes	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☐ ☐ No ☐ C ☐ Doors ☐ Broken Vapor ☐ No ☐	☑ Squeaks  l □ Po No Operates cover plates missin □ Walls □ Ce r Seals: □ Yes ☑ □ Missing □ Cra	or  ::  Yes  No  g  Safety Hazard  illings  No  N/A
Walls & Ceilin Floor: Ceiling Fan: Electrical: Heating/Cool Bedroom Egr Doors & Win GENERAL C #2 BEDROO	Moisture  ☐ Satisfa  Typical c ☐ N/A  Switches: Open grouing Source: ess Restricte dows:  COMMENTS M RIGHT Forelated equipments	ctory stains: ctory racks:  Yes und/Reverse po Yes d: N/A Operational: Locks/Latches RONT BOYS: ment is not part	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes S Operable:	Ory Outlets: Yes Holes: No No Yes Yes	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☐ ☐ No ☐ C ☐ Doors ☐ Broken Vapor ☐ No ☐	☑ Squeaks  l □ Po No Operates cover plates missin □ Walls □ Ce r Seals: □ Yes ☑ □ Missing □ Cra	or  :: ☑ Yes ☐ No  g ☐ <b>Safety Hazard</b> ilings  ☑ No ☐ N/A  acked Glass  ome; yellowed/original.
Walls & Ceiling Floor: Ceiling Fan: Electrical: Heating/Cool: Bedroom Egr Doors & Win GENERAL C #2 BEDROO! Smoke & CO	Moisture  ☐ Satisfa  Typical c ☐ N/A  Switches: Open grouing Source: ess Restricte dows:  COMMENTS M RIGHT Forelated equipments	ctory stains: ctory racks:  Yes und/Reverse po Yes d: N/A Operational: Locks/Latches RONT BOYS: ment is not part	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes S Operable:	Ory Outlets: Yes Holes: No No Yes Yes	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☐ ☐ No ☐ C ☐ Doors ☐ Broken Vapor ☐ No ☐	☑ Squeaks  l □ Po No Operates cover plates missin □ Walls □ Ce r Seals: □ Yes ☑ □ Missing □ Cra	or  :: ☑ Yes ☐ No  g ☐ <b>Safety Hazard</b> ilings  ☑ No ☐ N/A  acked Glass  ome; yellowed/original.
Walls & Ceiling Floor: Ceiling Fan: Electrical: Heating/Cool: Bedroom Egr Doors & Win GENERAL C #2 BEDROO! Smoke & CO	Moisture  ☐ Satisfa  Typical c ☐ N/A  Switches: Open grouing Source: ess Restricte dows:  COMMENTS M RIGHT Forelated equipments	ctory stains: ctory racks:  Yes und/Reverse po Yes d: N/A Operational: Locks/Latches RONT BOYS: ment is not part	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes S Operable:	Ory Outlets: Yes Holes: No No Yes Yes	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☐ ☐ No ☐ C ☐ Doors ☐ Broken Vapor ☐ No ☐	☑ Squeaks  l □ Po No Operates cover plates missin □ Walls □ Ce r Seals: □ Yes ☑ □ Missing □ Cra	or  :: ☑ Yes ☐ No  g ☐ <b>Safety Hazard</b> ilings  ☑ No ☐ N/A  acked Glass  ome; yellowed/original.
Walls & Ceiling Floor: Ceiling Fan: Electrical: Heating/Cool: Bedroom Egr Doors & Win GENERAL C	Moisture  ☐ Satisfa  Typical c ☐ N/A  Switches: Open grouing Source: ess Restricte dows:  COMMENTS M RIGHT Forelated equipments	ctory stains: ctory racks:  Yes und/Reverse po Yes d: N/A Operational: Locks/Latches RONT BOYS: ment is not part	☐ Yes ☐ Marginal ☑ Yes ☐ Satisfacto ☐ No olarity: ☐ No ☐ Yes ☑ Yes ☑ Yes S Operable:	Ory Outlets: Yes Holes: No No Yes Yes	✓ No ☐ Poor ☐ No ☐ Margina ✓ Yes ☐ ☐ No ☐ C ☐ Doors ☐ Broken Vapor ☐ No ☐	☑ Squeaks  l □ Po No Operates cover plates missin □ Walls □ Ce r Seals: □ Yes ☑ □ Missing □ Cra	or  :: ☑ Yes ☐ No  g ☐ <b>Safety Hazard</b> ilings  ☑ No ☐ N/A  acked Glass  ome; yellowed/original.

Page 37 of 47

## #3 BEDROOM CENTER

I OCATION:	CENTER GREEN				
	g: Satisfactory	☐ Marginal		□ Poor	
vvans ee cennig	Moisture stains:	□ Yes	•	✓ No Where:	
Floor:	☐ Satisfactory	✓ Marginal		☐ Poor ☐ Squeal	ks 🗹 Slopes
11001.	Typical cracks:	✓ Yes			as a stopes
Ceiling Fan:	✓ N/A	☐ Satisfacto	orv		l Poor
Electrical:	Switches: ✓ Yes	□ No	Outlets:	_	ates: ☑ Yes ☐ No
Electrical.	Open ground/Reverse po		☐ Yes	1	issing Safety Hazard
Heating/Coolin		□ No	Holes:		Ceilings
	ess Restricted: $\square$ N/A	☐ Yes	✓ No	_ Doors _ wans _	Comings
Doors & Wind		✓ Yes	□ No	Broken Vapor Seals:	Yes ☑ No □ N/A
Doors & William	Locks/Latcher		✓ Yes		Cracked Glass
		o operatione.			- Cracked Glass
GENERAL CO	OMMENTS				
	I FRONT GREEN CENT				
inaccessible. R	ecommend removing all ite	ms in closet a	nd inspect a	tic through knee wall befor	e closing.
	#4	<b>BEDRO</b>	OM F	ONT LEFT	
LOCATION:	GIRLS DANCER	1			
Walls & Ceiling	g: 🗹 Satisfactory	□ Marginal	[	□ Poor	
•	Moisture stains:	□ Yes		✓ No Where:	
Floor:	✓ Satisfactory	☑ Marginal		☐ Poor ☑ Squeal	ks 🗹 Slopes
	Typical cracks:	✓ Yes		□ No	•
Ceiling Fan:	☑ N/A	☐ Satisfacto	ory	☐ Marginal ☐	l Poor
Electrical:	Switches: ✓ Yes	□ No	<b>Outlets:</b>		ates: ☑ Yes ☐ No
	Open ground/Reverse po	larity:	☐ Yes		issing   Safety Hazard
Heating/Cooling		□ No	Holes:		l Ceilings
_	ess Restricted: \( \square\) N/A	☐ Yes	✓ No		
Doors & Wind		✓ Yes	□ No	Broken Vapor Seals:	Yes ☑ No □ N/A
	Locks/Latche	s Operable:	Yes		Cracked Glass
CENEDAL				Č	
GENERAL CO					
#4 REDROOM	A FRONT LEFT ·				

## WINDOWS/FIREPLACES/HALL/ATTIC

	DOWS / GLAS					
					(See remarks pag	
					ws under warranty	
Evidence of Broke					Needed: ☐ Yes	
☐ Glazing compor		Cracked glass	☐ Hardware mis		ken counter-balan	
Security Bars Pres	ent: ☑ N/A ⊔	Yes ⊔ No ⊔ No	t tested $\square$ Safety I	hazard ⊔ Test rele	ase mechanism bef	ore moving in
FIREPLACE	□ None Lo	cation(s): family	(gas)			
☑ Recommend hav						
			ned on before clos	sing & test firepla	ce	
					have evaluated/ser	viced by plumber
or fireplace compa	,		S	e ,		J 1
Material:		asonrv 🗆 Meta	al (pre-fabricated)	☐ Metal insert		
Miscellaneous:					<i>r operates</i> : □ Yes	□ No
			els should be sea	-	place doors need	
Damper Modified					4	<b>4</b>
Hearth Adequate					quate $\square$ Loo	
Physical Conditio				detery = 11de	quate <u>—</u> 200	se/imssing
				_		_
STAIRS / STEPS			Satisfactory	☐ Marginal	□ Poor _	☐ None
Handrail:		•	☐ Marginal		ety hazard 🛭 Loos	
Risers/Treads:	✓ Sat	tisfactory [	☐ Marginal	$\square$ Poor $\square$ <i>Rise</i>	ers/Treads uneven	/unsafe
SMOKE / CARBO	ON MONOXID	E DETECTORS	(See remark	s page)		
Present:	Smoke Detecto		,	Operates:	☐ Yes ☐ No	✓ Not tested
	CO Detector:	✓ Yes		Operates:	☐ Yes ☐ No	✓ Not tested
				•		
Security systems,		f n and the like are	e not part of a ho	me inspection (se	e contract). Foll	ow up with the
provider for these features in home to have them inspected or evaluated.						
provider for these	e features in hor	ne to have them	inspected or eval	uated.		
✓ Not tested; Sho			-		y.	
☑ Not tested; Sho	ould be perform	ed by Local/Stat	e municipality pr		y.	
✓ Not tested; Sho	ould be perform URE/FRAMIN	ed by Local/Stat G/INSULATION	e municipality pr	rior to Occupanc		TENTER □ Other
✓ Not tested; Sho ATTIC/STRUCT Access:	ould be perform  URE/FRAMIN   Stairs	ed by Local/State G/INSULATION Pull down	e municipality pr  N/A  Scuttle hole/ce	rior to Occupancy		<i>ENTER</i> □ Other
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From:	ould be perform  URE/FRAMIN  ☐ Stairs  ☑ Access pane	ed by Local/State  G/INSULATION  Pull down  In the	e municipality pr  N/A Scuttle hole/ce e attic	rior to Occupancy	) ☑ No access- C	<i>EENTER</i> □ Other
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location:	ould be perform  URE/FRAMIN  □ Stairs  ☑ Access pane □ Bedroom ha	ed by Local/State  G/INSULATION  Pull down  In the Bedr	e municipality pr  N/A  Scuttle hole/ce	rior to Occupancy		<i>ENTER</i> □ Other
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By	URE/FRAMIN  ☐ Stairs  ☑ Access pane ☐ Bedroom ha y: no flooring, lo	ed by Local/State  G/INSULATION  Pull down  In the Bedroose insulation	e municipality promote N/A  N/A  Scuttle hole/ce e attic coom closet	rior to Occupancy illing-bedroom(girls  Other  Garage	) ☑ No access- C	<i>ENTER</i> □ Other
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring:	URE/FRAMIN  ☐ Stairs  ☑ Access pane ☐ Bedroom ha y: no flooring, lo ☐ Complete	ed by Local/State  G/INSULATION  Pull down  In the Bedra Bed	e municipality pr  N/A  Scuttle hole/ce e attic room closet	rior to Occupancy illing-bedroom(girls	) ☑ <i>No access- C</i> ☐ Other	
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By	URE/FRAMIN  ☐ Stairs  ☑ Access pane ☐ Bedroom ha y: no flooring, lo ☐ Complete Type: fiberglas	ed by Local/State  G/INSULATION  Pull down  In the line Bedre Bedr	e municipality pr  N/A  Scuttle hole/ce e attic room closet  al s	rior to Occupancy illing-bedroom(girls	Other  3-6 Approx. R-r	rating: Unknown
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation:	URE/FRAMIN  ☐ Stairs  ☑ Access pane ☐ Bedroom ha y: no flooring, lo ☐ Complete Type: fiberglas ☐ Damaged	G/INSULATION  Pull down  In the last Bedresse insulation  Particles  Batts  Displaced	e municipality pr N/A N/A Scuttle hole/ce e attic room closet al s	iling-bedroom(girls	Other  3-6 Approx. R-r  Recommend	rating: Unknown Baffles @ Eaves
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring:	URE/FRAMIN  □ Stairs  ☑ Access pane □ Bedroom ha y: no flooring, lo □ Complete Type: fiberglas □ Damaged □ Rafters	G/INSULATION Pull down In the Image of the I	e municipality provided in the control of the contr	iling-bedroom(girls	Other  3-6 Approx. R-r	rating: Unknown Baffles @ Eaves
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In:	URE/FRAMIN  Stairs  Access pane Bedroom ha y: no flooring, lo Complete Type: fiberglas Damaged Rafters Recommend	G/INSULATION Pull down In the Image of the I	e municipality property N/A  N/A  Scuttle hole/ce e attic room closet  al  Loose  Missing  Between ceiling	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists	Other  3-6 Approx. R-r  Recommend  Not visible	rating: <mark>Unknown</mark> Baffles @ Eaves
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In:  Note: Insulations	Duld be perform  URE/FRAMIN  □ Stairs  □ Access pane □ Bedroom ha y: no flooring, lo □ Complete Type: fiberglas □ Damaged □ Rafters □ Recommend in older homes m	ed by Local/State  G/INSULATION  Pull down  In the line Bedre  Cose insulation  Partices  Batts  Displaced  Walls  d additional insulation	e municipality pr  N	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists walls, ceilings, cr	Other  Other  Approx. R-r  Recommend  Not visible  awl or basement;	rating: Unknown  Baffles @ Eaves  not visible where
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In:  Note: Insulations finished or inacces	URE/FRAMIN  □ Stairs  ☑ Access pane □ Bedroom ha y: no flooring, lo □ Complete Type: fiberglas □ Damaged □ Rafters □ Recomment in older homes n sible. It is alway	GINSULATION  Pull down  In the line Bedresose insulation  Partices  Batts  Displaced  Walls  d additional insulation insulation insulation insulation.	e municipality pr  N/A  Scuttle hole/ce e attic room closet  al s	iling-bedroom(girls	Other  Other  Approx. R-r  Recommend  Not visible  awl or basement; portractor that provi	rating: Unknown  Baffles @ Eaves  not visible where ides that service.
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In:  Note: Insulations	URE/FRAMIN  □ Stairs □ Access pane □ Bedroom ha y: no flooring, lo □ Complete Type: fiberglas □ Damaged □ Rafters □ Recommend in older homes n sible. It is alway □ Yes	ed by Local/State  G/INSULATION  Pull down  In the line Bedresse insulation  Particles Batts  Displaced  Walls  d additional insulation and be very little of sever secommended to the control of the line by the	e municipality property of the N/A  N/A  Scuttle hole/ce e attic room closet  al  Loose  Missing  Between ceiling of the non-existent in conduct an energiation appears addition	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists walls, ceilings, crey audit with a coequate Recurrence	Other  Other  Geommend Not visible  awl or basement; antractor that provious mend addition.	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In:  Note: Insulations finished or inacces	URE/FRAMIN  □ Stairs □ Access pane □ Bedroom ha y: no flooring, lo □ Complete Type: fiberglas □ Damaged □ Rafters □ Recomment in older homes in sible. It is alway □ Yes □ Maximum v	G/INSULATION  Pull down  In the last Bedresse insulation  Batts  Displaced  Walls  d additional insulation  res recommended to the last Bedresse insulation  Wentilation is always be very little of the last Bedresse Bedr	e municipality provided in the control of the contr	iling-bedroom(girls	Other  Other  Approx. R-r Recommend Not visible  awl or basement; rentractor that provious ommend additioning life of roof, avoid	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation id hot humid
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In:  Note: Insulations finished or inacces	URE/FRAMIN  □ Stairs  ☑ Access pane □ Bedroom ha y: no flooring, lo □ Complete  Type: fiberglas □ Damaged □ Rafters □ Recomment in older homes in sible. It is alway ☑ Yes ☑ Maximum v conditions of	G/INSULATION  Pull down  In the line Bedresose insulation  Particles  Displaced  Walls  d additional insulation  No Venture  Ventilation is alway a conducive to mole	e municipality provided in the control of the contr	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists  walls, ceilings, cr gy audit with a co equate Technology Rece to avoid shortenin	Other  Other  Approx. R-r Recommend Not visible  awl or basement; reportered that provide the providence of the providen	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In: Note: Insulations finished or inacces Ventilation:	URE/FRAMIN  Stairs  Access pane Bedroom ha y: no flooring, lo Complete Type: fiberglas Damaged Rafters Recommend in older homes n sible. It is alway Yes Maximum v conditions of sheathing da	G/INSULATION Pull down In the left   In the left   Bedre left   Sose insulation   Particles   Batts   Displaced   Walls   d additional insulation   Walls   In the left   Particles   In the left   Bedre left   I	e municipality provided in the control of the contr	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists  walls, ceilings, cr gy audit with a co equate Tequate Acceptate Acce	Other  Other  Other  Approx. R-r  Recommend  Not visible  awl or basement; and tractor that provious on sheathing & ried contractor.	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation id hot humid rafters, heat build-up,
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In: Note: Insulations finished or inacces Ventilation:  Fans Exhausted To	URE/FRAMIN  Stairs  Access pane Bedroom ha y: no flooring, lo Complete Type: fiberglas Damaged Rafters Recommend in older homes n sible. It is alway Yes Maximum v conditions o sheathing da IN/A	G/INSULATION Pull down In the left   In the left   Bedre left   Sose insulation   Particular   Sose insulation   Particular   Sos   Batts   Displaced   Walls   d additional insular   In the left   Walls   d additional insular   In the left   Pull down   In the left   Bedre left   In the left   In th	e municipality provided in the conduct an energy recommended in growth, condensate went in the conduct and energy recommended in growth, condensate wentilation & insurance in the conduct in the conduct and energy recommended in growth, condensate wentilation & insurance in the conduct in the conduct and energy recommended in growth, condensate wentilation & insurance in the conduct in the conduct and insurance in the c	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists  walls, ceilings, cr. gy audit with a co equate No avoid shortenin ation/rusted nails/fre lation with a qualifi No Outside	Other  Other  Other  Approx. R-r  Recommend  Not visible  awl or basement; and tractor that provious of the of roof, avoing life of roof, avoing set on sheathing & sied contractor.  E: Yes \( \sum \) No	rating: Unknown  Baffles @ Eaves  not visible where ides that service.  al ventilation id hot humid rafters, heat build-up,  Not visible
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In: Note: Insulations finished or inacces Ventilation:  Fans Exhausted Tot HVAC Duct:	URE/FRAMIN  Stairs  Access pane Bedroom ha y: no flooring, lo Complete Type: fiberglas Damaged Rafters Recommend in older homes n sible. It is alway Yes Maximum v conditions o sheathing da : N/A Not visible	ed by Local/State  G/INSULATION  Pull down  In the line Bedresse insulation  Partice Batts  Displaced Walls  d additional insulation is alway be very little of the conducive to mole amage, etc. Discusse Attic:  Damaged	e municipality provided in the image of the	iling-bedroom(girls	Other  Other  Other  Approx. R-r  Recommend  Not visible  awl or basement; and tractor that provious of the of roof, avoing life of roof, avoing set on sheathing & sied contractor.  E: Yes \( \sum \) No	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation id hot humid rafters, heat build-up,
✓ Not tested; Sho  ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In:  Note: Insulations finished or inacces Ventilation:  Fans Exhausted To HVAC Duct: Chimney Chase:	URE/FRAMIN  □ Stairs □ Access pane □ Bedroom ha y: no flooring, lo □ Complete Type: fiberglas □ Damaged □ Rafters □ Recomment in older homes in sible. It is alway □ Yes □ Maximum v conditions of sheathing dat : □ N/A □ Not visible □ N/A	GINSULATION Pull down In the least pose insulation Bedresse insulation Batts Batts Displaced Walls Additional insulation way be very little of the conductive to molecular and the conductive	e municipality provided in the second closet  al Souttle hole/ce e attic room closet  al Loose	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists  walls, ceilings, crey audit with a coequate to avoid shortenination/rusted nails/frelation with a qualifi No Outside Disconnected Not visible	Other  Other  Other  Approx. R-r Recommend Not visible  awl or basement; r ontractor that provi ommend addition ag life of roof, avoi ost on sheathing & r ied contractor.  E: Yes No	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation id hot humid rafters, heat build-up,  Not visible  Repair/Replace
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In: Note: Insulations finished or inacces Ventilation:  Fans Exhausted To: HVAC Duct: Chimney Chase: Structural Proble	URE/FRAMIN  Stairs  Access pane Bedroom ha y: no flooring, lo Complete Type: fiberglas Damaged Rafters Recommend in older homes in sible. It is alway Yes Maximum v conditions of sheathing dates N/A Not visible N/A MS Observed:	G/INSULATION  Pull down  In the line Bedresse insulation  Batts  Displaced  Walls  d additional insulation  No Ventional ventilation is alway and conducive to molecular and conducive	municipality property of the municipality property of the municipality property of the municipality of the	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists  walls, ceilings, cr gy audit with a co equate Rece to avoid shortenin ation/rusted nails/fre lation with a qualifi No Outside Disconnected Not visible repair Rece	Other  Other  Other  Approx. R-r Recommend Not visible  awl or basement; rentractor that provious on sheathing & red contractor.  Example Yes No deal Leaking  ommend Structure	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation id hot humid rafters, heat build-up,  Not visible  Repair/Replace
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation:  Installed In:  Note: Insulations finished or inacces Ventilation:  Fans Exhausted To: HVAC Duct: Chimney Chase: Structural Proble Roof Structure:	URE/FRAMIN  Stairs  Access pane Bedroom ha y: no flooring, lo Complete Type: fiberglas Damaged Rafters Recommend in older homes in sible. It is alway Yes Maximum v conditions of sheathing da I N/A Not visible N/A Rafters Rafters	G/INSULATION  Pull down  In the left Bedresse insulation  Batts  Displaced  Walls  d additional insulation is alway be very little of the rentilation is alway conducive to moleumage, etc. Discuss Attic:  Damaged  Satisfactory  Yes No  Trusses	e municipality provided in the provided in th	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists  walls, ceilings, crey audit with a coequate to avoid shortenination/rusted nails/frelation with a qualifi No Outside Disconnected Not visible	Other  Other  Other  Approx. R-r Recommend Not visible  awl or basement; r ontractor that provi ommend addition ag life of roof, avoi ost on sheathing & r ied contractor.  E: Yes No	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation id hot humid rafters, heat build-up,  Not visible  Repair/Replace
✓ Not tested; Sho ATTIC/STRUCT Access: Inspected From: Location: Access Limited By Flooring: Insulation: Installed In: Note: Insulations finished or inacces Ventilation:  Fans Exhausted To: HVAC Duct: Chimney Chase: Structural Proble	URE/FRAMIN  Stairs  Access pane Bedroom ha y: no flooring, lo Complete Type: fiberglas Damaged Rafters Recommend in older homes in sible. It is alway Yes Maximum v conditions of sheathing da I N/A Not visible N/A Rafters Rafters	ed by Local/State  G/INSULATION  Pull down  In the line Bedresse insulation  Partices  Displaced  Walls  d additional insulation is alway be very little of the conducive to moleumage, etc. Discuss Attic:  Damaged  Satisfactory  Yes No  Trusses  No	municipality property of the municipality property of the municipality property of the municipality of the	iling-bedroom(girls Other Garage  None Average inches: Compressed ing joists  walls, ceilings, cr gy audit with a co equate Tequate No Outside Disconnected Not visible repair Reco	Other  Other  Other  Approx. R-r Recommend Not visible  awl or basement; rentractor that provious on sheathing & red contractor.  Example Yes No deal Leaking  ommend Structure	rating: Unknown Baffles @ Eaves  not visible where ides that service. al ventilation id hot humid rafters, heat build-up,  Not visible  Repair/Replace

Evidence of Condensation/Moisture Leaking:   Yes No (See remarks page) Possible Mold where leaks in home; testing and identification of mold and environmental hazards is NOT part of home inspection an environmental testing contractor before closing for that type of inspection.  Ceiling Joists:   Wood Metal Other Not visible  Vapor Barriers:   Kraft/foil faced Plastic Not visible Improperly inspection.	1. Follow-up
Firewall Between Units:  \( \subseteq \text{N/A} \) Yes \( \subseteq \text{No} \) \( \subseteq \text{Needs repair/sealing} \) (See remarks page)  Indication of Past fire damage \( \supseteq \text{Yes} \) \( \supseteq \text{No} \) \( \supseteq \text{Recommend checking with Local fire Marshall and Town Electrical: \( \supseteq \text{Open junction box(es)} \) \( \supseteq \text{Handyman wiring} \supseteq \text{Visible knob-and-tube} \supseteq \text{Loose visible knob-and-tube} \)	nship
SGENERAL COMMENTS	
WINDOWS/FIREPLACES/HALL/ATTIC: There are older windows. Plan & budget for repairs & replation of the repair in the state of the repair in the	clutter in the inspect attice in in hallways; er room on fir outside; taining the ational Fire Sa
CONCERNS:	
unknown.	

Page	40	of	47
------	----	----	----

## FINISHED BASEMENT

STAIRS N/A Condition: Handrail: Headway Over Stairs:	✓ Satisfactory ✓ Yes ✓ Satisfactory	☐ Marginal ☐ No ☐ <i>Low clearan</i>		☐ Typi ondition:   <i>Safety haza</i>	ical wear and tea    Satisfacto	
Material: Horizontal Cracks: Step Cracks: ☑ Inaccess Vertical Cracks: Covered Walls: Movement Apparent: Indication of Moisture: storage everywhere	☑ Poured concret ☑ Inaccessible/f ible/finished walls ☑ Inaccessible/f ☑ Inaccessible/f ☑ Inaccessible f ☑ inaccessible to	te  Covered wall inished walls inished walls inished walls inished walls inished walls	s, ceiling ar	nd flooring- st	tructure inaccess	rniture, inaccessible sible
BASEMENT/CRAWL SP	ACE WALLS				North	
Diagram	indicates where wa	all not visible			DS	
and type of P = Panel D = Dryw S = Stora; O = Other	vall ge	C = Crack(s) M = Monitor E = Evaluate	West	DS	DS DS South	<b>DS</b> East
	☑ Concrete ctory ☐ Marginal	☐ Dirt/Grav		l Not visible □ Large cra		basement cluttered
Insulation Comments: insulation (between floor jo performed on the home before Company for information and	ists). Energy losse ore closing to find	areas that need in	ed or identi	fied in a gen	neral inspection	n. Have an Energy audit
	Unknown/not Check all area Check all area Yes □ No □ Mold, etc. are No ded for legal bedro other requirements utilities or laundry accessible <b>Tested:</b> Yes □ No ☑ No seen weather cond ast. Observing produy. It is strongly	as for moisture & Fresh  Old state that of a NJ Horomore of the Polymer of the NJ Horomore of the NJ Horomor	WDI when thins me Inspection code officement may be rescence posture and vinage, work install a W	ion (See State deemed by ial evaluate affect over a tested-clutte resent	andards of Prace local township any basements all health and be the recommend delation can occur systems and sun	which requires Egress for purpose other than reathing.  which requires Egress for purpose other than reathing.  where the cover-inaccessible humidifier  where if a basement has the pumps is imperative

				, ,	Page 41 of 47
GIRDERS / BEAMS / CO		ent- inaccessible to se	l view		☑ Finished ge, WDI, etc.
Condition:	☐ Satisfactory	☐ Marginal	☐ Poor	☐ Stained/rusted	I
JOISTS Material: Condition:	☐ Wood ☐ Steel ☐ Satisfactory	☐ Truss ☐ Marginal	Not visible  ☐ Poor		
☑(IF CHECKED)Wood dinsulation/walls or ceilings Hidden damage possible. For company exterminate prior	must be removed to Recommend structur	o determine extent o	lamage as per s	tructural carpente	r's evaluation.
SUB FLOOR  ☐ Indication of moisture sta GENERAL COMMENTS		s around shower stall	s, etc., as viewe	d from basement or	crawl space
The basement was finished a insulation on foundation wal See garage section comment pump; inaccessible. Recompactivate, submersible type go avoid water infiltration. Recompactivate dehumidifier for moisture correquired by township before CONCERNS:  1. Obtain all closed permits. The basement was finish. There was insulation or invasive inspection. Second	Ills, sills, etc.; structur ts & separate NPMA- mend having storage o on when water leve commend cleaning an ontrol as good practic e closing.  ts for finished basen hed and structure w n foundation walls, s	re completely covered as Termite report. The removed & cover and rises). Recommend maintaining gutter the country of the count	d and cannot be The sump pump d test pump before d observing proper and leaders for permits for finis d rooms as requisive to for evide completely cove	removed in a non-in had storage over covere closing (needs to per grading and drain proper water drainageshed basement, bath whired by township bance of water/seepagered and cannot be	evasive inspection.  In a ver and around  In a have float type to large on exterior to large. Recommend a laroom, and rooms as the process of the large of the la

### **PLUMBING**

WATER SERVICE		ff Location: basem		
			pairs/upgrades at some point- monit	or plumbing
Water Entry Piping:			mited view 🗹 Copper/Galv.	
		, CPVC, <b>Polybutylene</b> , P		☐ Unknown
Visible Water Distribution			✓ Plastic* (PVC, CPVC, Polybutylene, P	EX) 🛘 Unknown
Condition:	☑ Satisfactory		□ Poor	
Lead Other Than Solde	r Joints: ☐ Yes	☑ No	☐ Unknown ☐ Service entry	
<b>Functional Flow:</b>	✓ Adequate □	Low Door	☐ Water pressure over 80 psi; high	
Pipes, Supply/Drain:	<b>☑</b> Corroded	☑ Leaking	☐ Valves broken/missing ☐ Di	ssimilar metal
Drain/Waste/Vent Pipe:	inaccessible-	completed covered/f	inished basement	☑ PVC ☑ ABS
Condition:			ncealed/finished rooms & basement	
	Cross connectio	n:	☑ No	
Support/Insulation:	Type:			
Traps Proper P-Type:	: □ N/A	✓ Yes	☐ No; some S-type or other <b>☑ P-</b>	traps recommended
Functional Drainage:		□ Poor	☐ Recommend plumber evaluate	•
Interior Fuel Storage			Leaking: ☐ Yes ☐ No	
Gas Line:	•		☐ Stainless steel ☐ Flexible CSST (	vellow)   Not visible
Condition:	☑ Satisfactory		Poor	<b>,</b> · · · · · · · · · · · · · · · · ·
	•	C		
✓ NOTE: T-Valves, b	all valves, gate va	lves or any shut off	valves, are not tested in a New Jersey	home inspection.
MAIN FUEL SHUT-(	OFF LOCATION	By Gas meter	n/A	
FIXTURES IN HOMI		,	ing and upgrades must be installed by l	icensed plumber and
			when renovated.	F
Note: Fixtures in home	are not inspected		uality, manufacturer, expected life or p	oredicted failure.
			ny noted leaks or corrosion at time of i	
life service is a concern				•
WELL PUMP	✓ N/A	☐ Submersible		
✓ Well system and war	ter testing not part	of NJ home inspect	ion. Well inspection and water testing	should be conducted
prior to closing.		_	-	
SANITARY / GRIND	ED DIIMD	✓ N/A		
WATER HEATER #1			☐ Satisfactory ☐ Marginal	✓ Old*
Brand name:	Bradford white	Condition:	Satisfactory & Marginar	E Old.
Type:	☑ Gas	☐ Electric	☐ Oil ☐ Other	
Unit Elevated:	☐ Yes ☐ No	□ N/A	☐ Tank/Piping corroded/leaking	
Capacity:	~75 gallons	□ IN/A	Approximate age: ~2004 year(s) (11	******
Combustion Air Venting		$\square$ No $\square$ N/A	Seismic restraints needed: Yes	
Relief Valve:	✓ Yes □ No		oer: ☑ Yes ☐ No ☐ Missing	☐ Recommend repair
Vent Pipe:			etory $\square$ Pitch proper $\square$ Rusted	☐ Recommend repair
vent ripe:	— FVC- Iligil ell	inciency L Sausiac	tiony in Filen proper in Kusteu	□ Kecommena repair
WATER SOFTENER	(Unit not ev	aluated) ☑ N/A		
<b>Loop Installed:</b>	☐ Yes ☐ No	Plumbing Hoo	ked Up: □ Yes □ No	
<b>Softener Present:</b>	☐ Yes ☐ No	Plumbing Leal	king: □ Yes □ No	
NOTE: Homes with h	ard water will ofte	n need a water softe	ner system to avoid damaging mineral	huildun or correcion to
			er softener company and plumber if the	
			home is left vacant for a period of time	
			s, washers, dishwashers, hot water hear	
			ard water (calcium or mineral build-up	
	•		and water (calcium of finiteral bund-up in y and fixtures evaluated by a licensed	
			nnections and iron in plumbing pipes s	
			racks and clogs. Have plumber upgrad	

Plumbing code or any other code inspection in NOT performed in a general home inspection. Seek out a licensed plumber or

township code officer for that type of inspection.

#### **GENERAL COMMENTS**

**PLUMBING:** There was a white PVC pipe in attic that appears to come from the powder room on first floor; have plumber evaluate and verify/identify. If it's a plumbing vent, they should go through the roof to outside; unknown. Have a licensed plumber evaluate plumbing (kitchen fixture/leaking, corrosion, noisy dosposer, running toilet, etc.) and make repairs & upgrades where needed. The hot water heater was original to home or approximately 11 yrs. old. A typical life expectancy is ~ 10 yrs, and often less when there is hard water/rust in the home. Recommend upgrading/replacing the hot water tank to avoid flooding the finished basement should unit break and leak. \* The hot water heater was power assisted and the sewer ejector pump for basement bathroom was present and needs power to eliminate waste & water. The hot water heater and the basement bathroom will not function without power. Consider a back-up power generator in case of extended power outage to the home. Discuss options with a licensed electrician to run essential items (ex-sump pump, sewer ejector pumps, sump pumps, refrigerator, HVAC, etc.). There was rust/calcium/mineral deposits on fixtures, shower heads & plumbing (valves, fittings, piping, etc.); indicative of hard water in home. Note that fixtures, drains and pipes may clog, leak or back-up when a home in left vacant for a period of time and if there is hard water in home. Homes with hard water will often need a water softener system to avoid damaging mineral buildup or corrosion to plumbing supply lines, drains and fixtures. Confer with a water softener company and plumber if there is hard water in the home. Testing for hard water is not part of an inspection. If a home is left vacant for a period of time, it can clog fixtures resulting in loss of flow, hot or cold water. Toilets, bathrooms, washers, dishwashers, hot water heaters or any other appliance in a home can become damaged or fail because of hard water (calcium or mineral build-up) at any time even after an inspection. Get the water tested by a water softener company and fixtures evaluated by a licensed plumber before closing. Discuss water descaler units with a licensed plumber to help control hard water (ex-scale buster, eddy, Vulcan, etc. among others on market). Recommend a camera inspection of sewer lines to rule out cracks, roots, obstructions or damage; follow-up with a plumbing or a Roto-rooter type company. Recommend maintaining water & sewer main line insurance to help defray costs of main line repairs. Check with the local utilities or Water Company for participating insurers if available. Older homes can also have rusty water from street pipes or connections and iron in plumbing pipes such galvanized pipes. These can corrode and rust from inside out and cause leaks, cracks and clogs. Have plumber upgrade older plumber in home. Plumbing code or any other code inspection in NOT performed in a general home inspection. Seek out a licensed plumber or township code officer for that type of inspection. All homes will need plumbing repairs (leaks, clogs, corrosion, upgrades, repairs, etc.) at any time in the life of the home. Plan and budget for these repairs and upgrades. Only a licensed plumber should make these repairs.

- 1. There was rust/calcium/mineral deposits on fixtures, shower heads & plumbing (valves, fittings, piping, etc.); indicative of hard water in home. Note that fixtures, drains and pipes may clog, leak or back-up when a home in left vacant for a period of time and if there is hard water in home. Homes with hard water will often need a water softener system to avoid damaging mineral buildup or corrosion to plumbing supply lines, drains and fixtures. Also discuss water descalers with a plumber (ex- scale buster, eddy, Vulcan, etc. among others on market).
- 2. The hot water heater was original to home or approximately 11 yrs. old. A typical life expectancy is  $\sim$  10 yrs. and often less when there is hard water/rust in the home. Recommend upgrading/replacing the hot water tank to avoid flooding the finished basement should unit break and leak.\*
- 3. The hot water heater was power assisted and the sewer ejector pump for basement bathroom was present and needs power to eliminate waste & water. The hot water heater and the basement bathroom will not function without power. Consider a back-up power generator in case of extended power outage to the home. Discuss options with a licensed electrician to run essential items (ex- sump pump, sewer ejector pumps, sump pumps, refrigerator, HVAC, etc.).
- 4. Have a licensed plumber evaluate plumbing (kitchen fixture/leaking, corrosion, noisy dosposer, running toilet, etc.) and make repairs & upgrades where needed. The hot water heater was original to home or approximately 11 yrs. old. A typical life expectancy is ~ 10 yrs. and often less when there is hard water/rust in the home. Recommend upgrading/replacing the hot water tank to avoid flooding the finished basement should unit break and leak. The hot water heater was power assisted and the sewer ejector pump for basement bathroom was present and needs power to eliminate waste & water. There was a white PVC pipe in attic that appears to come from the powder room on first floor; have plumber evaluate and verify/identify. If it's a plumbing vent, they should go through the roof to outside; unknown.

## HEATING

HEATING SYSTEM	
	Brand name: American Std. Approximate age: newer (8-2014) Brand name: Carrier (original) Approximate age: 11 yrs.
Ducts:	
Warm Air System:	✓ Belt drive ☐ Direct drive ☐ Gravity ✓ Central system ☐ Floor/Wall unit
Heat Exchanger:	✓ N/A (sealed) □ Visual w/mirror □ Flame distortion □ Rusted □ Carbon/soot buildup
Carbon Monoxide:	□ N/A □ Detected at Plenum/Register □ Not tested
CO Test:	$\square$ Yes $\square$ No <i>Combustion Air Venting Present:</i> $\square$ Yes $\square$ No $\square$ N/A
Controls:	Disconnect: ✓ Yes ☐ No ✓ Normal operating and safety controls observed
Distribution:	✓ Metal duct ☐ Insul. flex duct ☐ Cold air returns ☐ Duct board ☐ Asbestos-like wrap
Flue Piping:	□ N/A □ Rusted □ Improper slope □ Safety hazard
Supports for Piping/In Filter:	asulation: ☑ N/A ☐ Yes ☐ No ☑ Standard ☐ Electrostatic ☑ Satisfactory ☐ Needs cleaning/replacement ☐ Missing
	Thermostat: ✓ Fired ☐ Did not fire Proper Operation: ✓ Yes ☐ No ☐ Not tested
Heat Pump:	☐ Aux. electric ☐ Aux. gas ☑ N/A Sub-Slab ducts: ☐ Yes ☐ No ☑ N/A
System Not Operated 1	e
	ician examine yearly System Condition:  Satisfactory*
to closing. The inspec	Etechnician examine yearly, obtain township code inspections for Fire and HVAC sub codes prior etion is not required to determine heat supply adequacy or distribution balance for the home or VAC contractor or boiler contractor evaluate the adequacy and required size needed before closing.
	☐ Recommend testing prior to <i>closing</i>
OTHER SYSTEMS GENERAL COMME	✓ N/A ☐ Electric baseboard ☐ Radiant ceiling cable
required by township properly. The other Recommend a yearly	as a newer A/C outside and furnace; American Std.; obtain all closed permits for installations as before closing.* Typical life of a higher efficiency type unit is ~ 10 yrs. when maintained furnace is older or original to the home; plan on replacement at any time due to old age. furnace & A/C service/maintenance as well as chimney cleaning/inspections for fire/life/safety. 0, 60, 90 day filers, washable filters, etc.; personal choice.

Page	45	of	47
------	----	----	----

## COOLING

COOLING SYSTEM	<i>I</i> – UNIT #1			ge: 11 yrs. and new	er unit.			
<b>Energy Source:</b>	Electric	☐ Gas	☐ Water	☐ Other				
Unit Type:	Air cooled	☐ Water cooled	☐ Gas chiller	☐ Geothermal	☐ Heat pump			
Evaporator Coil:	☐ Satisfactory	✓ Not visible	☐ Needs cleaning	, ,				
Refrigerant lines:	$\square$ Leak	□ Damage	☐ Insulation m	0	Satisfactory			
Condensate Line/Drain	<b>n:</b> $\square$ To exterior	☐ To pump	☐ Floor drain	☐ Laundry sink	☐ Other			
Temperature Differe	ential: Unit 1?	??? °F Unit 2 ??? °F						
	Difference in ten	nperature (split) should	l be 15-22° Fahren	heit <i>(See remarks p</i>	page)			
Compressor Conditi	Compressor Condition: ☐ Satisfactory ☐ Marginal ☐ Poor ☐ Rusted ☐ Damaged							
Operation:	Satisfactory:	l Yes □ No 🔽	Not operated due to a	<mark>exterior temperature</mark>				
☑ Recommend HVAC	T technician examine	c/clean/service yearly						
Note: If present, thro	ough wall and wind	dow A/C units produc	ee moisture and m	nay potentially leak	into interior walls			
		an cause damage to a						
					oved. Such removal is			
		and therefore is limite						
		o rule out water or co						
periodically to inspec			•	5				
GENERAL COMM	ENTS							
<b>COOLING:</b> The outside temperature was 55°F and too cool to test the air conditioning. Recommend testing the A/C when warmer before closing. There was one older/original (11 yrs.) and a newer condenser. There should be at least three consecutive days & nights of 60-65F temperatures when using the air conditioner to avoid damaging the condenser unit "Slugging." <b>CONCERNS:</b>								
1. Follow-up: Test cooling systems before closing when warmer and able to test properly; too cool to test ( nights went down below 55F and cool days).								
	v	,						

### **ELECTRICAL**

MAIN PANEL	Location: basement	Condition:	✓ Satisfactory	☑ no spares "Cutler Hammer Panel"		
Adequate Clearan	ce To Panel: 🗹	Yes □ No Amp	erage: 200 Volts 120/24	0		
Appears Grounded	l: ☑ Yes □	No ☐ Not visible				
G.F.C.I. present:	$\square$ Yes $\square$	No <b>Oper</b>	ative:	)		
A.F.C.I. present:		_	Operative: ☐ Yes ☑ Not tested- will shut down items in home			
MAIN WIRE:	☐ Copper 🗹	☐ Copper ☑ Aluminum ☐ Copper clad aluminum ☐ Tin clad copper ☐ Not visible				
$\square$ Tapping before the main breaker $\square$ Double tapping of the main wire						
Condition:	☐ Satisfactor	y 🔲 Poor	☐ Federal Pacific P	anel Stab Lok® <i>(See remarks page)*</i>		
<b>Predominant BRANCH WIRE:</b> ☑ Copper ☐ <b>Aluminum*</b> ☐ Copper clad aluminum ☐ Not visible						
Condition:	☐ Satisfactor	y 🔲 Poor	☐ Poor ☐ Recommend electrician evaluate/repair*			
	Romex	☐ BX cable	☐ Conduit	☐ Knob & tube**		
	☐ Double tapping ☐ Wires undersized/oversized breaker/fuse					
☑ Read REMARKS addendum to report- "tripping breakers"						
SUB PANEL(S)   ☑ None apparent □ Breakers □ Fuses						
ELECTRICAL FIXTURES						
A representative number of installed lighting fixtures, switches, and receptacles located inside the house, garage, and exterior						
walls were tested and found to be:						
Condition:	☑ Satisfactor	y   Marginal	☐ Poor ☑ Not ac	cessible, clutter, furniture		
	☐ Open groui	nds 🛘 Reverse polari	ty GFCIs not opera	ting		
☐ Solid conductor aluminum branch wiring circuits* (See remarks page)						
☑ Obtain all closed electrical permits as required by Twp. Before closing						
☐ Recommend electrician evaluate/repair*						

#### GENERAL COMMENTS

**ELECTRICAL:** There was a Twp. Permits sticking on the PVC pipe for the sewer ejector pump; rough out indicated. Recommend obtaining all closed permits for finished basement before closing. The trim around the garage doors were torn and need replacement to keep out rodents, water, weather elements. Mice and rodents can chew on electrical wiring and cause damage and health issues. Test ARC fault breakers in panel when items shut down to avoid damage to plugged items (computers, etc.). There were visible power strips and extension cords in the home; not safe/fire safety hazard (can overload circuits). Each family has different electrical requirements or needs. If more power is needed, discuss needs with electrician and have added. The bathrooms were on the master bathroom circuit; if tripped, rest in this bathroom. Blow dryer(s) will trip the bathroom outlets. Discuss options such as dedicated circuits to each bathroom if dryers and other heated hand held appliances will be used often. Do not use extension cords, multiplier adapters or power strips to add more power; fir safety concern. If a breaker or circuit is tripped more than once, it is recommended to have an electrician evaluate circuits and have items separated by a licensed electrician. Items such a sump pumps, garage door openers, A/C units, stoves refrigerators or other heavy draw appliances should be on separate dedicated circuits.

- 1. There was a Twp. Permits sticking on the PVC pipe for the sewer ejector pump; rough out indicated. Recommend obtaining all closed permits for finished basement before closing.
- 2. The trim around the garage doors were torn and need replacement to keep out rodents, water, weather elements. Mice and rodents can chew on electrical wiring and cause damage and health issues.
- 3. There were visible power strips and extension cords in the home; not safe/fire safety hazard (can overload circuits). Each family has different electrical requirements or needs. If more power is needed, discuss needs with electrician and have added.

### SUMMARY

Repairs are recommended for any comments or defects that are stated in this report. Every home must be maintained and will require repairs. Problems will occur and things will break. This report is designed to help reduce the possibility, but will not eliminate them from happening. Issues can and will arise at any time, budget accordingly. Recommend checking with local authorities for permits on additions and alterations. Please be advised that it is important to read the entire report and the remarks pages that are sent separately to the client. These remarks pages contain important maintenance information that the client needs to be aware of. All homes will need repairs, routine maintenance and upgrades over the course of its life. Addressing plumbing, heating, electrical and other mechanical problems or issues as they occur, with qualified contractors, should be done to keep home maintained properly. Older homes will often require structural upgrades when renovations are made. These will be dictated by the engineer and or architect designing the renovation or modification to bring structure up to current building practices and township specifications. It is recommended to obtain township permits for history of home. Recommend a "Home Warranty." Roof leaks are number one cause of water damage to interior of home. Damage can often be concealed inside walls of interior and often revealed either when renovations are done or when water issue is ongoing for a period of time. Water damage can include structural as well as environmental manifestations such as mold and mildew among others. All roofs should be inspected yearly, gutters cleaned several times a year. These systems must be maintained to provided a water tight cladding to protect the home. Often a damage found does not necessarily correspond to the roof directly above, but at some other part of the roof. Water can travel below the surfaces of roof and end up in any number of places that are hidden or concealed. A general visual home inspection cannot open up walls, ceilings, flooring or guess what is behind them. This uncertainty is always possible when roof, flashing, siding and all exterior systems are not maintained.

"If there is anything in the report that you do not understand you <u>must contact us promptly prior to closing</u>. If not addressed, any ignored item(s), misunderstood or overlooked as to their importance and implication(s,) can and frequently do, result in negative outcome and incur costs to repair or replace." Please read REMARKS addendum as it is part of the report and contains important information. Any areas reported as inaccessible and not inspected or evaluated must be made accessible and inspected prior to the closing.

#### All items must be addressed and repaired prior to closing.

\* Items listed in this report may inadvertently have been left off the Summary Sheet. Customer should read the entire report, including the Remarks. Boxed area may have been checked or unchecked inadvertently- written comments are most important and purposely written into report which may not reflect boxed area checked.